



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

KIA
Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	<table> <tr> <td>Cust No/Name</td><td>/KHOO LAY KEONG, ANDREW</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMJ8048D / 21/03/201</td></tr> <tr> <td>Date In/Mileage</td><td>/ 0</td></tr> <tr> <td>Chassis No</td><td>KNAF3416MK5032377</td></tr> <tr> <td>Engine No</td><td>G4FGJH723741</td></tr> <tr> <td>Make/Model</td><td>KIA/CERATO 1.6 A EX G333</td></tr> <tr> <td>Colour/Trim</td><td>SWP SNOW WHITE PEAR/ WK SATURN BLACK</td></tr> </table>	Cust No/Name	/KHOO LAY KEONG, ANDREW	Reg No/Reg Date	SMJ8048D / 21/03/201	Date In/Mileage	/ 0	Chassis No	KNAF3416MK5032377	Engine No	G4FGJH723741	Make/Model	KIA/CERATO 1.6 A EX G333	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK
Cust No/Name	/KHOO LAY KEONG, ANDREW														
Reg No/Reg Date	SMJ8048D / 21/03/201														
Date In/Mileage	/ 0														
Chassis No	KNAF3416MK5032377														
Engine No	G4FGJH723741														
Make/Model	KIA/CERATO 1.6 A EX G333														
Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	29/12/2021/ 18:48	BLE	261 / Edwin Caina	44837
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW RR BUMPER, RR END PNL & BOOTLID @400				1600 2800.00
	REPAIR RHR FENDER, LHR FENDER & RR FLR PNL				
E PNT98000	RESpray RR BUMPER, RR END PNL, RR FLR PNL, BOOTLID, @350				2100.00
	LHR FENDER & RHR FENDER				
E PNT88000	REMOVE & REFIT BOOTLID COMPONENT				120.00
E PNT88000	REMOVE & REFIT RR FLR BOARD, TRIM & CARPET				120.00
A 54900099	CHECK WIRING ELECTRICAL SYSTEM				30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
M SUNDRY	SUPPLY RR NUMBER PLATE WITH CASING				50.00
E PNT88000	REMOVE & REFIT REVERSE SENSOR				60 80.00
M SUNDRY	SUPPLY REVERSE SENSOR?				Xm? 220.00
M SUNDRY	APPLY ANTI CORROSION ON AFFECTED AREAS				40.00
M SUNDRY	SUPPLU BODY PNL SEALANT				40.00
M SUNDRY	SUPPLY C&C BADGE				40.00
M SUNDRY	Sundries				20.00
M COVER-RR BUMPER		1.00	651.00	20.00	520.80
M COVER-RR BUMPER LWR		1.00	241.00	20.00	192.80
M COVER-RR BUMPER UNDER, LH		1.00	33.00	20.00	26.40
M COVER-RR BUMPER FOG LAMP, LH		1.00	19.00	20.00	15.20
M COVER-RR BUMPER FOG LAMP, RH		1.00	19.00	20.00	15.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	<table> <tr> <td>Cust No/Name</td><td>/KHOO LAY KEONG, ANDREW</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMJ8048D / 21/03/201</td></tr> <tr> <td>Date In/Mileage</td><td>/ 0</td></tr> <tr> <td>Chassis No</td><td>KNAF3416MK5032377</td></tr> <tr> <td>Engine No</td><td>G4FGJH723741</td></tr> <tr> <td>Make/Model</td><td>KIA/CERATO 1.6 A EX G333</td></tr> <tr> <td>Colour/Trim</td><td>SWP SNOW WHITE PEAR/ WK SATURN BLACK</td></tr> </table>	Cust No/Name	/KHOO LAY KEONG, ANDREW	Reg No/Reg Date	SMJ8048D / 21/03/201	Date In/Mileage	/ 0	Chassis No	KNAF3416MK5032377	Engine No	G4FGJH723741	Make/Model	KIA/CERATO 1.6 A EX G333	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK
Cust No/Name	/KHOO LAY KEONG, ANDREW														
Reg No/Reg Date	SMJ8048D / 21/03/201														
Date In/Mileage	/ 0														
Chassis No	KNAF3416MK5032377														
Engine No	G4FGJH723741														
Make/Model	KIA/CERATO 1.6 A EX G333														
Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	29/12/2021/ 18:48	BLE	261 / Edwin Caina	44837
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M LAMP ASSY-SIDE T/SIGNAL, LH	Xnn	1.00	181.00	20.00	144.80
M LAMP ASSY-SIDE T/SIGNAL, RH	Xnn	1.00	181.00	20.00	144.80
M EXTN WIRING ASSY-BWS	Xnn	1.00	207.00	20.00	165.60
M BEAM-RR BUMPER	Xnn	1.00	318.00	20.00	254.40
M STAY-RR BUMPER LH	Xnn	1.00	65.00	20.00	52.00
M STAY-RR BUMPER RH	Xnn	1.00	65.00	20.00	52.00
M ANTENNA ASSY-SMARTKEY	Xnn	1.00	46.00	20.00	36.80
M BRACKET-RR BEAM UPR MTG, LH	Xnn	1.00	9.00	20.00	7.20
M BRACKET-RR BEAM UPR MTG, RH	Xnn	1.00	9.00	20.00	7.20
M BRACKET-RR BEAM LWR, CTR	Xnn	1.00	6.00	20.00	4.80
M BRACKET-RR BEAM LWR MTG	Xnn	2.00	6.00	20.00	9.60
M COVER-RR BUMPER UNDER, RH	Xnn	1.00	33.00	20.00	26.40
M BRACKET ASSY-RR BPR SIDE UPR, LH	Xnn	1.00	25.00	20.00	20.00
M BRACKET ASSY-RR BPR SIDE UPR, RH	Xnn	1.00	31.00	20.00	24.80
M PANEL ASSY-BACK	Xnn	1.00	324.00	20.00	259.20
M TRIM ASSY-RR TRANSVERSE	Xnn	1.00	41.00	20.00	32.80
M PANEL ASSY-TRUNK LID	Xnn	1.00	1297.00	20.00	1037.60
M HINGE ASSY-TRUNK LID, LH	Xnn	1.00	97.00	20.00	77.60
M HINGE ASSY-TRUNK LID, RH	Xnn	1.00	97.00	20.00	77.60
M W/STRIP-TRUNK LID OPNG	Xnn	1.00	100.00	20.00	80.00
M LATCH ASSY-TRUNK LID	Xnn	1.00	112.00	20.00	89.60
M STRIKER ASSY-TRUNK LID	Xnn	1.00	40.00	20.00	32.00
M LOGO ASSY-KIA SUB	Xnn	1.00	32.00	20.00	25.60
M EMBLEM-CERATO	Xnn	1.00	28.00	20.00	22.40
M LAMP ASSY-CENTER GARNISH	Xnn	1.00	690.00	20.00	552.00
M LAMP ASSY-REAR COMB INSIDE, LH	Xnn	1.00	608.00	20.00	486.40
M LAMP ASSY-REAR COMB INSIDE, RH	Xnn	1.00	608.00	20.00	486.40
M LAMP ASSY-REAR COMB OUTSIDE, LH	Xnn	1.00	675.00	20.00	540.00
M LAMP ASSY-REAR COMB OUTSIDE, RH	Xnn	1.00	675.00	20.00	540.00

SURVEYOR NAME: Rasul-Hp 90510068

SURVEYOR SIGNATURE: Rasul

Confirm & accepted by

DATE: 30/12/21 @ 1500

REMARKS:

EXCESS: TBA / REPAIR

8 days + 2 = 10 days
Rising before print

Nett	11,840.00
7% GST on	828.80
Total Payable	12,668.80

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.