



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21013313/Bqf3n2	Date: 06/04/2022
			Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMS 4663G	Veh. Inspected	SNB 2697A	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10013134/KY	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	30/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA YARIS CROSS	c.c	1490	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	MXPB102010034	Colour	BLUE	
Odometer	4188 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	205/65 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	205/65 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	205/65 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/12/2021	Inspection Date	30/12/2021	
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	