



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21013315/Uvf3n2	
			Date: 17/01/2022	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHB 1172A	Veh. Inspected	SJB 3678X
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/12/21/2055	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	30/12/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HONDA STREAM (A)	c.c	1799
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	JHMRN68408S201295	Colour	BLACK
	Odometer	501656 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	205/65 R15	MICHELIN	6 mm
	L/H Front Tyre	205/65 R15	MICHELIN	6 mm
	R/H Rear Tyre	205/65 R15	MICHELIN	6 mm
	L/H Rear Tyre	205/65 R15	MICHELIN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	21/12/2021	Inspection Date	07/01/2022
	Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	