

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD		Ref:	CS/SMR21013315/Uvf3n2
60 WOODLANDS INDUSTRIAL PARK		Date:	17/01/2022
E4SINGAPORE 757705		Code:	SMR
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 1172A	Veh. Inspected	SJB 3678X
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/12/21/2055	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	30/12/2021
2. Vehicle Particulars & Condition			
Make & Model	HONDA STREAM (A)	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JHMRN68408S201295	Colour	BLACK
Odometer	501656 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/65 R15	MICHELIN	6 mm
L/H Front Tyre	205/65 R15	MICHELIN	6 mm
R/H Rear Tyre	205/65 R15	MICHELIN	6 mm
L/H Rear Tyre	205/65 R15	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	21/12/2021	Inspection Date	07/01/2022
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.			
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	