



FORMTEAM ADJUSTERS PTE LTD

No.33, Ubi Ave 3
#02-15, Vertex
Singapore 408868

Tel : (65) 6509 1788
Fax : (65) 6509 6221

Email: claims@fta.com.sg

Co.Reg No: 201212134W

GST Reg No: 201212134W

Our Reference : FTA/AHA/2106/19336

Your Reference: 8442030120SG

Date : 29-Jun-2021

Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
Singapore 079120

Attention : Mr Bennie Tan

Dear Sir/Mdm,

RE-INSPECTION OF VEHICLE NO . JRH 4250

Pursuant to your instructions on 10-Jun-2021 , we have conducted a reinspection of the above vehicle at 8 Kaki Bukit Avenue 4 #02-46 Premier@KB Singapore 415875 on X.

We recommend a repair cost of **\$1,594.00** (see report) based on part by part repair and the estimated duration of repairs would take **05 days** .

We also enclosed our note of charges for your consideration.

Thank you for this assignment.

Your faithfully

FormTeam Adjusters Pte Ltd
Adjusters & Surveyors (Licensed Appraiser)

Ng You Han
Automobile Appraiser

(Email : yhng@fta.com.sg)

Encl. Re-inspection Report

AUTOMOBILE ASSESSMENT REPORT

PAGE : 1

Our Reference : FTA/AHA/2106/19336Your Reference : 8442030120SG

Date : 29-Jun-2021

Attention : Mr Bennie Tan

TO : Motor Claims Department

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16

Singapore 079120

Dear Sir/Madam,

Vehicle No : JRH 4250Model : Nissan Almera 1.5AMileage : 233779 kmChassis No : PN8B8AN17TCB03524Workshop : M/S Kompressor Automotive Workshop

Pursuant to your instructions on **10-Jun-2021**, we have conducted a reinspection of the above vehicle at **8 Kaki Bukit Avenue 4 #02-46 Premier@KB Singapore 415875** on **X**.

We are pleased to submit hereunder our adjustment which we trust should serve your purpose: -

QTY	DESCRIPTION	CONDITION	REMARKS	SUBMITTED	REVISED
	<u>PARTS REPLACEMENT-LIST ITEMS</u>				
1	Front Bumper	Minor Scratches	Respray	316.80	-
2	Front Bumper Side Retainer	Not Necessary		44.20	-
1	Front Bumper Chrome Trim	Not Consistent		108.60	-
1	LH Front Fender	Minor Scratches	Repair	457.40	-
1	LH Front Fender Splash Shield	Reuse		-	-
1	LH Front Door	Minor Scratches	Repair	1,123.90	-
1 Set	LH Front Door Frame Black Sticker	Not Necessary		35.10	-
1	LH Headlamp Assy	Not Consistent		359.50	-
1	LH Front Lower Arm	Not Consistent		207.20	-
1	LH Knuckle Arm	Not Consistent		376.90	-
1	LH Knuckle Arm Bearing	Not Consistent		106.50	-
	Sub-Total			3,136.10	-
	Discount Percentage 10%			313.61	-
	Total Parts List Items			2,822.49	-

FORMTEAM ADJUSTERS PTE LTD

PAGE : 2

Our Reference : FTA/AHA/2106/19336

Your Reference : 8442030120SG

QTY	DESCRIPTION	CONDITION	REMARKS	SUBMITTED	REVISED
	<u>PARTS REPLACEMENT-SPECIAL NETT ITEMS</u>				
1	LH Front Sport Rim	Scraped	Deformed	520.00	400.00
1	LH Front Tyre	Not Consistent		255.00	-
8	LH Front Fender Splash Shield Clip	Necessary		24.00	24.00
1 Set	Front Shock Absorber	Not Consistent		800.00	-
10	Front Bumper Clip	Necessary		30.00	30.00
	Total Parts Special Nett Items			1,629.00	454.00
	Total Parts			4,451.49	454.00

Our Reference : FTA/AHA/2106/19336Your Reference: 8442030120SG

QTY	DESCRIPTION	SUBMITTED	REVISED
	<u>LABOUR & MISC</u>		
1	Labour charges to dismantle and remove all damaged parts, renew and install the same; to cut out the damaged body panels, renew and weld the same; to panel beat and straighten affected areas. (including all repair parts)	500.00	400.00
2	Spray painting charges to putty and spray paint the front bumper, front fender, front door and necessary areas.	750.00	650.00
3	To spray anti-rust protection for the affected parts and areas.	60.00	-
4	To check wiring.	30.00	30.00
5	To align headlamps and refocus headlamp beams.	60.00	-
6	To remove and transfer front door glass and fittings.	60.00	-
7	To remove and replace damaged left hand front suspension and undercarriage parts.	300.00	-
8	To conduct wheel alignment before repair.	60.00	-
9	To conduct wheel alignment after repair.	60.00	60.00
	Total Labour Amount	1,880.00	1,140.00
	Total Parts and Labour	6,331.49	1,594.00

Our Reference : FTA/AHA/2106/19336

Your Reference: 8442030120SG

QTY	DESCRIPTION	SUBMITTED	REVISED
	Our Recommended Repair Cost (see remarks)		
		\$5,100.00	\$1,594.00

REMARKS :

Our recommended Part By Part Repair Cost is **\$1,594.00** (instead of the submitted repair cost of **\$5,100.00** .In normal circumstances, repairs to the vehicle would take approximately **05 days** to complete. Please find enclosed our note of charges for your kind attention.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by **FORMTEAM ADJUSTERS PTE LTD** for any reliance on this report by any third party, unless with the permission of the addressee.

Yours faithfully,

FORMTEAM ADJUSTERS PTE LTD

Frankie Pang
AMSAE(AUST), AMIRTE, AMSOE,
MASPACI, MSAAA
Licensed Appraiser

Ng You Han
Automobile Appraiser

FormTeam Adjusters Pte Ltd

Vehicle No: JRH 4250

Workshop: Kompressor Automotive Workshop

Accident Date: 18 November 2020

No. 33 Ubi Ave 3
#02-15 Vertex
Singapore 408868

Tel : (65) 6509 1788
Fax : (65) 6509 6221

Email: claims@fta.com.sg

www.fta.com.sg

Co. Reg No: 201212134W

GST Reg. No: 201212134W





















































