



DATE :
VEHICLE : 53K 8201H
MAKE / MODEL : Hyundai Kona
CHASIS NO. :

CLAIM DETAIL : PARTS

[illegible]

TOTAL PRICE	\$	9,762.00
LESS 20%	\$	1,952.40

SUB TOTAL PRICE \$ 7,809.60

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	BONNET RUBBER	1	\$ 45.00	\$ 45.00
2	BONNET INSULATOR		\$ 175.00	\$ 175.00
3	FRONT BUMPER CLIP (SET)	1	\$ 80.00	\$ 80.00
6	HEAD LAMP CLIP (SET)	1	\$ 60.00	\$ 60.00
7	FRONT FENDER SEALANT RH	1	\$ 80.00	\$ 80.00
8	FRONT FENDER INNER TRIM CLIP (SET)	1	\$ 80.00	\$ 80.00
9				

TOTAL \$ 520.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,000.00	300 400.
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	300
3	TUFF COAT	\$ 250.00	X un
4	WIRING AND BULB CHECK	\$ 180.00	30.
6	REMOVE AND REFIX SENSOR AND DISTANCE SETTING	\$ 80.00	X un
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 250.00	150 ✓

TOTAL \$ 2,760.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,329.60
TOTAL LABOUR COST : \$ 2,760.00
TOTAL REPAIR COST : \$ 11,089.60

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

2173.92
50
880
3103.92
41592500, 3 days
Tanfikh 17495719.
WP 3/1/22 @ 1745
tanfikh @ 11h40pm
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item must be approved and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date: