

TK MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56

SINGAPORE 417883

TEL : 96273323 FAX 68442641

CO.REG NO. : 53049097-L

TP Ergo.
Denise.

LEE KIM SIA

BLK 101, PASIR RIS STREET 12, #10-15

SINGAPORE 510101

DATE : 13/4/2022

ACCIDENT DATE 27/12/2021

MODEL : MERCEDES BENZ GLC250 4MATIC COUPE AMG LINE (R19 LED)

CHASSIS NO. : WDC2533462F318973 /-

ESTIMATE COST OF REPAIRS TO MERCEDES BENZ CAR NO. : SMZ64A

1 PC FRONT BUMPER <i>Deformed</i>	\$ 2,490.00 NETT	1915
12 PC FRONT BUMPER CLIP <i>new</i>	\$ 60.00 NETT	30
1 PC FRONT BUMPER L/H SIDE RETAINER <i>new</i>	\$ 48.00 NETT	✓
2 PC FRONT BUMPER L/H PARKING SENSOR <i>and</i>	\$ 312.00 NETT	✓
1 PC FRONT BUMPER L/H LOWER GARNISH <i>new</i>	\$ 98.00 NETT	✓
1 PC FRONT BUMPER L/H LOWER GARNISH CHROME <i>new</i>	\$ 116.00 NETT	✓
1 PC FRONT BUMPER SPONGE <i>cracked</i>	\$ 260.00 NETT	180
1 PC FRONT L/H HEADLAMP	\$ 4,000.00 NETT	3500
1 PC FRONT L/H HEADLAMP CLIP <i>new</i>	\$ 48.00 NETT	20
1 PC FRONT GRILLE (AMG LINE R19 LED) <i>cracked</i>	\$ 788.00 NETT	✓
1 PC FRONT GRILLE EMBLEM <i>new</i>	\$ 178.00 NETT	✓
8 PC FRONT GRILLE CLIP <i>new</i>	\$ 40.00 NETT	✓
1 PC FRONT WIPER TANK <i>Deformed</i>	\$ 368.00 NETT	258
1 PC FRONT BONNET <i>Dented</i>	\$ 3,218.00 NETT	2343
2 PC FRONT BONNET HINGES <i>new</i>	\$ 224.00 NETT	✓
1 PC FRONT BONNET EMBLEM <i>new</i>	\$ 78.00 NETT	✓
1 PC FRONT L/H FENDER <i>Distorted</i>	\$ 1,152.00 NETT	1020
1 PC FRONT L/H FENDER INNER SHIELD <i>Deformed</i>	\$ 278.00 NETT	✓
1 PC FRONT L/H FENDER EMBLEM <i>new</i>	\$ 160.00 NETT	✓
1 PC FRONT L/H FENDER ARC GARNISH <i>Deformed</i>	\$ 378.00 NETT	✓
12 PC SIDE SKIRT CLIP <i>new</i>	\$ 48.00 NETT	✓
1 PC FRONT L/H LOWER ARM <i>new</i>	\$ 872.00 NETT	✓
1 PC FRONT L/H KNUCKLE ARM <i>new</i>	\$ 732.00 NETT	✓
1 PC FRONT L/H KNUCKLE HUP & BEARING <i>new</i>	\$ 492.00 NETT	✓
1 PC FRONT L/H SHOCK ABSORBER	\$ 958.00 NETT	✓
1 PC FRONT L/H SPORT RIM <i>new</i>	\$ 1,860.00 NETT	✓

LABOUR CHARGE

TO SPRAY PAINTING
TO REMOVE AND REFIX FRONT R/H UNDER CARRIAGE
TO CHECK WIRING
TO CONDUCT COMPUTER ALIGHTMENT
TO REMOVE & REINSTALL FRONT BUMPER PARKING SENSOR , POSITION
CHECK & TEST FOR FUNCTIONING ALL SENSOR
TO RESET FAULT CODE & CARRY OUT DIAGNOSTIC CHECK
TO PANEL BEATING , WELDING , REMOVING ALL DAMAGED PARTS
& REPLACING OF THE NEW PARTS ETC.

~~\$ 1,200.00~~ 900
~~\$ 380.00~~ X 100
~~\$ 50.00~~ 30
~~\$ 90.00~~ 80
~~\$ 80.00~~ 60
~~\$ 120.00~~ ✓
~~\$ 950.00~~ 800

1990

TOTAL : \$ 22,126.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 12363.40
2/s: 8.9K.
05 Days.

TK MOTOR WORKSHOP

