

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013333/AQY3Q2**Date:** 14/03/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00056972100
Claimant Vehicle No :	SMX5571E	Insured Vehicle No :	SLB2669E
Date of Loss:	26/12/2021	Nature of Claim:	TP
		Claim No:	SNM21D207688/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX5571E	Engine No:	HRA2152412A
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T (A)	Chassis No:	SJNFEAJ11U1425489
Reg. Date:	08/08/2015 (Man. Year: 2015)	Odometer:	119497 km
Colour:	Maroon		
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,354.40	4,304.95	3,049.45	41.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	830.00	620.00	42.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,804.40	5,134.95	3,669.45	41.68
Approved Total (Overridden) (\$\$)		4,100.00		
Nett Amount (\$\$)	8,804.40	4,100.00	4,704.40	53.43

INSPECTION

Date of Assignment:	03/01/2022	Automobile Hub Enterprise
Date Inspected:	31/12/2021 Inspected At:	1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT
Estimated Period of Repair:	4.0 days	Singapore 417883

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Mar 2022)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX5571E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Not Necessary	30.00 FS	*- FS
2	1		*FRONT NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
3	1		*FRONT BUMPER	Deformed	689.80 F	*689.80 FL
4	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
5	1		*FRONT BUMPER SIDE HOLDER	N/S Damaged	51.80 F	*25.90 FL
6	1		*FRONT BUMPER TOW COVER	Not Necessary	28.20 F	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Dented	457.70 F	*457.70 FL
8	1		*FRONT BUMPER REINFORCEMENT LOWER	Not Necessary	337.30 F	*- FL
9	1		*FRONT BUMPER SPONGE	Cracked	195.70 F	*195.70 FL
10	1		*FRONT BUMPER FOG LAMP LH	Cracked	279.20 F	*279.20 FL
11	1		*FRONT BUMPER FOG LAMP COVER LH	Cracked	102.00 F	*102.00 FL
12	1		*FRONT BUMPER LOWER GARNISH	Deformed	284.80 F	*284.80 FL
13	1		*FRONT GRILLE	Cracked	461.20 F	*461.20 FL
14	1		*FRONT GRILLE CHROME MOULDING	Not Necessary	160.80 F	*- FL
15	1		*FRONT GRILLE LOGO	Necessary	109.20 F	*109.20 FL
16	1		*FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
17	1		*HEADLAMP LH	Cracked	2,961.00 F	*1,617.00 FL
18	1		*FRONT LH FENDER	Repair	622.70 F	*- FL
19	1		*FRONT LH FENDER ARC GARNISH	Cracked	483.00 F	*483.00 FL
20	1		*FRONT LH FENDER ARC GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,354.40	4,775.50
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	470.55
Total Parts (\$)	7,354.40	4,304.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	400.00
2	SPRAY PAINTING	New	600.00	400.00
3	WIRING	New	50.00	30.00
Gross Labour Cost (\$\$)			1,450.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >