

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21013335/TNY3E2**Date:** 16/11/2022**REFERENCE**

Insured/Claimant: MOHAMMAD NOOR ALIF BIN BUNGSU

Policy No: 7210070567

Date of Loss: 25/12/2021

Nature of Claim: OD

Claim No: 8570971416SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FBP9311K**

Make & Model: YAMAHA AEROX 155A, 155cc

Engine No: G3J8E0111177

Reg. Date: 05/07/2019 (Man. Year: 2019)

Chassis No: MH3SG4640KJ058363

Colour: Red/Black

Odometer: 62411 km

Engine Capacity: 155 cc

Market Value/New Car Price: S\$10,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 120/70 R14

Rear Tyre Size: 140/70 R14

Front Left Side: MITAS 5 mm

Rear Left Side: MITAS 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,734.70	2,487.70	1,247.00	33.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,480.00	300.00	1,180.00	79.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,214.70	2,787.70	2,427.00	46.54
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	4,914.70	2,487.70	2,427.00	49.38
+ GST 7.00/7.00% (S\$)	344.03	174.14	169.89	49.38
Nett Amount (S\$)	5,258.73	2,661.84	2,596.89	49.38

INSPECTION

Date of Assignment: 30/12/2021

Date Inspected: 14/01/2022

Inspected At:

Bike Production Pte Ltd (HQ)

610 SERANGOON ROAD

Singapore 218216

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$280.00 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WHEEL AXLE	Not Necessary	65.00 FL	*- FL
2	1		*LEFT FORK ASSY	Not Necessary	405.00 FL	*- FL
3	1		*STEERING STEM	Not Necessary	220.00 FL	*- FL
4	2		*STEERING STEM BEARINGS	Not Necessary	90.00 FL	*- FL
5	1		*HANDLE BAR	Bent	165.00 FL	*165.00 FL
6	1		*LEFT VIEW MIRROR	Cut	45.00 FL	*45.00 FL
7	1		*LEFT REAR FOOT REST	Cut	45.00 FL	*45.00 FL
8	1		*BRAKE LEVER LEFT	Cut	48.00 FL	*48.00 FL
9	1		*BALANCER LEFT	Cut	40.00 FL	*40.00 FL
10	1		*CENTRE COVER INNER BODY	Deformed	195.00 FL	*195.00 FL
11	1		*CENTRE COVER LOWER	Cut	140.00 FL	*140.00 FL
12	1		*LEFT FOOTSTEP	Deformed	185.00 FL	*185.00 FL
13	1		*BODY COVERSET DECALS	Cut	125.00 FL	*125.00 FL
14	1		*BODY COVERSET	Cut	495.00 FL	*495.00 FL
15	1		*AIRBOX ASSY	Cut	195.00 FL	*195.00 FL
16	1		*NVX AMBLEM	Cut	35.00 FL	*35.00 FL
17	1		*MAINSTAND	Bent	145.00 FL	*145.00 FL
18	1		*LEFT ENGINE COVER	Cut	135.00 FL	*135.00 FL
19	1		*BOX RACK	Not Necessary	195.00 FS	*- FS
20	1		*TOP BOX	Cut	280.00 FS	*280.00 FS
21	1		*FRONT SPORT RIM	Not Necessary	350.00 FS	*- FS
22	1		*LEFT FOOTSTEP LOWER Supplementary	Cut	115.00 FL	*115.00 FL
23	1		*HEADLAMP ASSY Supplementary	Broken	345.00 FL	*345.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,058.00	2,733.00
- List Item Discount on L Items 10.00/10.00% (\$)	323.30	245.30
Total Parts (\$)	3,734.70	2,487.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES (* Check)	New	100.00	0.00
2	REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS, CHECK WIRING AND LIGHTING SYSTEM	New	700.00	300.00
3	TO REMOVE, REPLACE AND BALANCE FRONT WHEEL RIM	New	120.00	0.00
4	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING	New	380.00	0.00
5	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES (* Check)	New	180.00	0.00
			Gross Labour Cost (\$\$)	1,480.00
				300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >