



√870 Y

Labour charges

Remove/refit rear tail-gate glass

Check and recoonect wiring

To anit- rust proofing

Remove/refit rear tail-gate mechanism to new door.

balance b/f \$6,793.70

\$120.00

\$40.00 20/

\$100.00 301

\$100.00 Gal