



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:YVONNE			Ref: CC4/ASM21013341/Aga3q2 Date: 20/07/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 2905R	Veh. Inspected	SLM 364P	
Policy No.	P2419138	Coverage (\$)	0.00	
Claim No.	S1M03PE4	Excess (\$)	0.00	
Assign From		Assign Date	30/12/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA ESTIMA	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	ACR507050730	Colour	BLACK	
Odometer	251065 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	245/40 R19	TOYO	6 mm	
L/H Front Tyre	245/245/40 R1940 R19	TOYO	6 mm	
R/H Rear Tyre	245/40 R19	TOYO	6 mm	
L/H Rear Tyre	245/40 R19	TOYO	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	26/12/2021	Inspection Date	30/12/2021	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	