

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AXA	DATE	: 27-Dec-21
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SLM364P		
MODEL	: TOYOTA ESTIMA 2.4A		
CHASSIS NO			
ACCIDENT DETAILS		DATE	: 26-Dec-21
		TIME	: 15:40HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Dehnd</i>	1	\$ 1,855.30	\$ <u>1,855.30</u>
2	FRONT BUMPER SIDE RETAINER <i>RH Dmgd</i>	2	\$ 88.60	\$ 177.20
3	HEADLAMP RH <i>ct</i>	1	\$ 2,366.50	\$ <u>2,366.50</u>
4	FRONT FENDER RH <i>Distorted</i>	1	\$ 640.00	\$ 640.00
5	FRONT FENDER WHEEL COWLING <i>Deformed</i>	1	\$ 220.00	\$ 220.00
6	FRONT FENDER LOWER PROTECTION RH <i>new</i>	1	\$ 90.50	\$ 90.50
7	WASHER TANK	1	\$ 210.20	\$ 210.20
8	WASHER TANK MOTOR	1	\$ 255.60	\$ 255.60
9	FRONT KNUCKLE ARM RH <i>not</i>	1	\$ 590.00	\$ 590.00
10	FRONT LOWER ARM RH <i>new</i>	1	\$ 695.00	\$ 695.00
11	FRONT KNUCKLE ARM BEARING RH	1	\$ 570.00	\$ 570.00
12	FRONT SHOCK ABSORBER RH	1	\$ 590.00	\$ 590.00

TOTAL PRICE \$ 8,260.30

LESS 25% \$ 2,065.08

SUB TOTAL PRICE \$ 6,195.23

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00

2	FRONT BUMPER SENSOR <i>Damaged.</i>	1	\$ 300.00	\$ 300.00	<i>200</i>
3	FRONT GRILLE <i>344</i>	1	\$ 1,100.00	\$ 1,100.00	<i>x</i>
4	FRONT FOGLAMP COVER <i>1 per</i>	1	\$ 180.00	\$ 180.00	<i>x</i>
5	FRONT FENDER COWLING CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	<i>✓</i>
6	FRONT WHEEL RIM RH <i>ut</i>	1	\$ 1,200.00	\$ 1,200.00	<i>500</i>
7	FRONT WHEEL TYRE RH <i>new</i>	1	\$ 350.00	\$ 350.00	<i>x.</i>

740

TOTAL \$ 3,170.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,000.00	<i>500.</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	<i>400</i>	
3	Tuff Coat	\$ 250.00	<i>30</i>	
4	WIRING CHECK	\$ 80.00	<i>30</i>	
5	REFOCUS HEADLAMP BEAM	\$ 60.00	<i>x</i>	
6	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 320.00	<i>x</i>	
7	FOUR WHEEL ALIGNMNET	\$ 120.00	<i>80.</i>	

1040

TOTAL \$2,830.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 9,365.23

TOTAL LABOUR COST : \$ 2,830.00

TOTAL REPAIR COST : \$ 12,195.23

total: 4893.25

1/3: 3.9K

04 days

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

**PART BY PART / LUMP SUM :
NO OF DAYS :**

FAX

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: