

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

30 DEC 2021

78, Shenton Way
AIG Building #07-16
Singapore 079120

Not Authorized
L1 Rep @ 2850/h
Resurvey After Paint
4 days

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle no: GBJ2585P

Accident involving vehicle no: SMY1689X/GBJ2585P

DOA: 29/12/2021 at SIMS AVENUE SLIP ROAD INTO PAYA LEBAR ROAD

Dear officer in charge

Estimate cost of repair for vehicle no: SMY1689X

To supplied:

Description	Qty	Amount	
Tailgate <i>953</i>	1	<i>RM</i> 997.10	✓
Tailgate absorber	2	<i>RM</i> 131.00	X
Tailgate lock	1	<i>RM</i> 98.90	X
Tailgate reflector	2	<i>ALSCM</i> 553.80	LT 276.90
Tailgate - H logo emblem	1	<i>RM</i> 24.70	—
Tailgate - HR-V emblem	1	<i>RM</i> 19.00	—
Tailgate - i-V Tec emblem	1	<i>RM</i> 16.00	✓
End panel	1	<i>RM</i> 411.90	X
End panel top garnish	1	<i>RM</i> 65.00	X
Boot weather strip	1	<i>RM</i> 95.80	X
Rear bumper	1	<i>RM</i> 532.10	✓
Tailamp	2	<i>ALSCM</i> 964.80	LT 482.40
Corner panel LH&RH	2	<i>ALSCM</i> 332.60	LT 166.30
Rear bumper sensor	2	<i>RM</i> 170.00	X
Corner panel sensor	2	<i>RM</i> 170.00	X
Tailgate outer handle panel	1	<i>ALSCM</i> 298.20	✓
Parts		4,880.10	
Parts less 20%		976.02	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

To remove/transfer rear windscreen glass to new door
To remove rear wiper assembly, tailgate top spoiler and
All attachments to new door

180.00 1201

To remove damaged parts & attachment

150.00 601

Cut & weld damaged panels

To straighten rear chassis where necessary

Repair/reshape damaged areas

Replace/align all parts into position

950.00

3001

Painting

1,100.00

7001

6,284.08