

# 威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,  
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com  
Business Regn No: 269436/00J

30 DEC 2021

78, Shenton Way  
AIG Building #07-16  
Singapore 079120

Attn: Motor claim dept-3<sup>rd</sup> party claim

Claiming against your insured vehicle no: GBJ2585P

Accident involving vehicle no: SMY1689X/GBJ2585P

DOA: 29/12/2021 at SIMS AVENUE SLIP ROAD INTO PAYA LEBAR ROAD

Dear officer in charge

Estimate cost of repair for vehicle no: SMY1689X

To supplied:

Description	Qty	Amount	
Tailgate	1	997.10	✓
Tailgate absorber	2	131.00	X
Tailgate lock	1	98.90	?
Tailgate reflector	2	553.80	LT
Tailgate – H logo emblem	1	24.70	—
Tailgate – HR-V emblem	1	19.00	—
Tailgate – i-V Tec emblem	1	16.00	✓
End panel	1	411.90	?
End panel top garnish	1	65.00	?
Boot weather strip	1	95.80	?
Rear bumper	1	532.10	✓
Tailamp	2	964.80	LT
Corner panel LH&RH	2	332.60	LT
Rear bumper sensor	2	170.00	?
Corner panel sensor	2	170.00	?
Tailgate outer handle panel	1	298.20	✓
Parts		4,880.10	
Parts less 20%		976.02	

Not Authorized  
L1 Rep @  
Resurvey After Paint  
4-5 days

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

To remove/transfer rear windscreen glass to new door	180.00	1201
To remove rear wiper assembly, tailgate top spoiler and All attachments to new door	150.00	601
To remove damaged parts & attachment		
Cut & weld damaged panels		
To straighten rear chassis where necessary		
Repair/reshape damaged areas		
Replace/align all parts into position	950.00	7
Painting	1,100.00	7001
	<hr/>	
	6,284.08	