

趙源摩托 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not authorized
Pharmacy B4 pain
3 days

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: **Third Party**

Date: **30.12.2021**

Accident Date : 17.12.2021

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

承接汽车烧焊喷漆及
代理各种车辆赔偿

ESTIMATE

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Honda Fit" Reg. No. SMY7738Z Claiming Against Your Insured Reg. No. SLM1425R		
1pc	Rear Bumper	5.50	<i>Bu</i> 1,025.00 ✓
10pcs	Rear Bumper Clips		<i>in</i> 55.00 ✓
1pc	Rear Bumper Corner Retainer RH		<i>in</i> 84.00 X
1pc	Rear Fender Splash Shield RH		<i>DiT</i> 165.00 ✓
	Less 20%		1,329.00 265.80 1,063.20
	To Conduct Electrical Check, Transfer Back Up Sensors, Rewiring, Bumper Boring etc		100.00 <i>150</i>
	To Respray, Repair Rear Wheel Rim		150.00 <i>600</i>
	To Conduct Computerize Wheel Alignment Test		80.00 <i>600</i>
	Labour Charge - Panel Beating, Repairing Of Rear O/S Fender, Inner Panel & Part Replacement		550.00 <i>4000</i>
	To Respray Affected Areas		550.00 <i>4000</i>
	Total :		2,493.20

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: