



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/1061/2021/JT
DATE	:	28-Dec-21
WIP	:	60492

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 29/12/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME	:	MS LIN JIA
ADDRESS	:	11 WOODGROVE WALK SINGAPORE 738154
TELEPHONE	:	HP +65 93879138
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2100397147-06
VEHICLE NO	:	SKQ 8249 C
MODEL CODE	:	AUDI A6 C7 2.0 TFSI MU
MODEL YEAR	:	29/12/2014
ENGINE NO	:	CDN 408652
CHASSIS NO	:	WAUZZZZG4EN140732
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	26-Dec-21
PLACE OF ACCIDENT	:	WOODLANDS AVE 1 TURNING INTO WOODLANDS AVE 3

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKSQ 8249 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. S/N \$	480.00 ✓	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE. S/N \$	400.00 ?	
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER, AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. ✓ ✓	\$ 3,200.00 1500	
4	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET. ✓	\$ 3,500.00 1650	
5	TO CARRY OUT DIAGNOSTIC CHECK. S/N \$	192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>7,772.00</u>	

PREMIUM AUTOMOBILES



55 UBI ROAD I, SINGAPORE 408699

TEL: 6366 2323 FAX: 6641 1183

EMAIL: NORA.KIAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKQ 8249 C

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Dented</i>	1	\$ 2,832.00	✓
2	FRONT BUMPER FIXING PATS <i>3 new</i>	1	\$ 276.00	x
3	FRONT BUMPER CLOSING ELEMENT	1	\$ 190.00	x
4	FRONT BUMPER GRILLE - LH <i>3 new</i>	1	\$ 153.00	x
5	FRONT BUMPER END CAP - LH	1	\$ 39.00	x
6	RADIATOR GRILLE <i>Cracked</i>	1	\$ 1,332.00	✓
7	RADIATOR GRILLE COVER	1	\$ 36.00	?
8	FRONT BUMPER FOAM FILLER PIECE	1	\$ 99.00	?
9	FRONT BUMPER SIDE REINFORCEMENT	1	\$ 872.00	?
10	FRONT BUMPER GUIDE PIECE - LH / RH <i>2 new</i>	2	\$ 76.00	x
11	FRONT BUMPER BRACE - LH <i>2 new</i>	1	\$ 30.00	x
12	FRONT BUMPER TOP COVER	1	\$ 123.00	?
13	CAUTION STICKER	1	\$ 14.00	?
14	AIR COND STICKER	1	\$ 30.00	?
15	FRONT PARKING AID SENSOR <i>2 new</i>	2	TBC	x
16	FRONT PARKING AID SENSOR SEAL RING - INNER / OUTER <i>2 new</i>	4	\$ 6.00	x
17	BONNET <i>Dented</i>	1	\$ 5,436.00	✓
18	BONNET ATTACHMENT PARTS <i>2 new</i>	1	\$ 144.00	x
19	BONNET LOCK BAR	2	\$ 100.00	?
20	BONNET BOWDEN CABLE - CENTER	1	\$ 58.00	?
SUB TOTAL SPARE PARTS		:	\$ 11,846.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKQ 8249 C

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	BONNET LOCK ?	2 \$	427.00 ?		
22	BONNET HOOD LATCH ?	1 \$	18.00 ?		
23	BONNET SWITCH ?	2 \$	148.00 ?		
24	BONNET RELEASE CABLE ?	1 \$	10.00 ?		
25	BONNET CATCH HOOK <i>new</i>	1 \$	140.00 x		
26	FRONT FENDER - LH <i>Buckled</i>	1 \$	1,391.00 ✓		
27	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1 \$	42.00 x		
28	FRONT FENDER STONE GUARD FILM - LH <i>new</i>	1 \$	121.00 ✓		
29	FRONT FENDER BRACE - LH ?	1 \$	96.00 ?		
30	FRONT WHEEL HOUSING LINER - LH <i>new</i>	1 \$	275.00 x		
31	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1 \$	80.00 x		
32	FRONT WHEEL SPOILER - LH <i>new</i>	1 \$	264.00 x		
33	HEADLIGHT MOUNTING - LH ?	1 \$	118.00 ?		
34	HEADLIGHT GAS DISCHARGE - LH ?	1 \$	3,321.00 ?		
35	LIFT CYLINDER <i>new</i>	1 \$	236.00 x		
36	LIFT CYLINDER HOSE	5 \$	191.00 ✓		
37	FRONT NO PLATE <i>new</i>	S/N \$	60.00 ✓		
37	SUNDRIES ?	\$	250.00 ?		
TOTAL SPARE PARTS		:	\$ 19,034.00		
TOTAL LABOUR CHARGES		:	\$ 7,772.00		
GRAND TOTAL		:	\$ 26,806.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Adrian Lim
: 29/12/21
:
:
:
:
: Not Authorised, 05 Days

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT