

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

AIG Asia Pacific Insurance Pte Ltd

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1060/2021/JT
DATE : 28-Dec-21
WIP : 60420

Xiao Chan.

\$6525.60

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 29/12/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR CHIANG SE SHENG
ADDRESS : BLK 59 PASIR RIS DRIVE 1
#16-18
SINGAPORE 519532
TELEPHONE : HP +65 84489923
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900166714-01
VEHICLE NO : SLC 205 T
MODEL CODE : AUDI A5 SB 2.0 TFSI
MODEL YEAR : 27/9/2019
ENGINE NO : CVK 087931
CHASSIS NO : WAUZZZF58KA076953
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Dec-21
PLACE OF ACCIDENT : WHITE SAND MALL CAR PARK



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLC 205 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$ 480.00	✓✓
2	TO REMOVE AND REINSTALL RHS DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$ 280.00	✓✓
3	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDERS AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 2,400.00	1000✓
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND FRONT RHS DOOR.	\$ 3,200.00	1650✓
6	TO RENEW RHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	X
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓✓
TOTAL LABOUR CHARGES		: \$ 7,472.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLC 205 T

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Dented</i>	1	\$ 2,251.00	✓ 1800.80
2	FRONT BUMPER FIXING PARTS <i>Neu</i>	1	\$ 407.00	+
3	FRONT BUMPER SECURING STRIP <i>Neu</i>	2	\$ 71.00	+
4	FRONT BUMPER GRILLE - CENTER <i>Neu</i>	1	\$ 196.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>Neu</i>	1	\$ 228.00	+
6	FRONT BUMPER AIR GUIDE - RH <i>Neu</i>	1	\$ 63.00	+
7	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Neu</i>	1	\$ 474.00	+
8	FRONT BUMPER GUIDE SECTION - RH <i>Neu</i>	1	\$ 36.00	+
9	FRONT FENDER - RH <i>Dented</i>	1	\$ 1,060.00	✓ 848
10	FRONT FENDER ATTACHEMENT PARTS <i>Neu</i>	1	\$ 53.00	? X
11	FRONT FENDER CLOSING ELEMENT - RH <i>Neu</i>	1	\$ 74.00	? X
12	FRONT FENDER BRACKET - RH <i>Neu</i>	1	\$ 35.00	? X
13	POP RIVET <i>Neu</i>	5	\$ 17.00	? 13.20
14	FRONT FENDER BRACKET CENTER - RH <i>Neu</i>	1	\$ 49.00	? X
15	FRONT FENDER BRACKET END - RH <i>Neu</i>	1	\$ 35.00	? X
16	FRONT FENDER BRACE - RH <i>Neu</i>	1	\$ 118.00	? X
17	FRONT FENDER CHROME TRIM - RH <i>Neu</i>	1	\$ 164.00	✓ 130.80
18	FRONT WHEEL HOUSING LINER - RH <i>Neu</i>	1	\$ 275.00	? X
19	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>Neu</i>	1	\$ 169.00	+
20	FRONT WHEEL SPOILER - RH <i>Neu</i>	1	\$ 73.00	+
SUB TOTAL SPARE PARTS			\$ 5,848.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLC 205 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER FLEDGE COVER LONG - RH <i>3 Not nec</i>	1	\$ 36.00	? X
22	FRONT FENDER FLEDGE COVER SHORT - RH	1	\$ 16.00	? X
23	HEADLIGHT <i>Not nec</i>	1	\$ 7,902.00	X
24	LIFT CYLINDER - RH	1	\$ 198.00	X
25	LIFT CYLINDER CORRUGATED PIPE <i>3 1/4"</i>	1	\$ 86.00	X
26	ALUMINIUM RIM <i>Not nec</i>	1	\$ 1,690.00	X
27	FRONT DOOR CHROME TRIM - RH <i>Nec</i>	1	\$ 164.00	✓ 130.80
28	SUNDRIES <i>Not nec.</i>		\$ 250.00	? X
TOTAL SPARE PARTS		:	\$ 16,190.00	
TOTAL LABOUR CHARGES		:	\$ 7,472.00	
GRAND TOTAL		:	\$ 23,662.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL NORAH.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

Adnan Lj
29/12/21

x160 Authorised, ~~05 Days~~ 04 Days.

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT