

Not Authorized
 Resurvey B4 paint
 82793.88 4 days



ESTIMATE TO REPAIR

VEHICLE NO. : SML 1211 J
 MAKE : HONDA
 MODEL : FIT 1.3 GF CVT
 YEAR : 2019
 CHASSIS NO : GK31346914

SURVEYOR NAME	: LKK
DATE OF SURVEY	: 30/12/21
TIME OF SURVEY	:

DATE : 28-Dec-21
 DATE OF ACCIDENT : 27-Dec-21
 THIRD PARTY REF : SMB 3005 C
 THIRD PARTY REF : TOWER TRANSIT

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper <i>510</i>				\$ Bu 529.60 ✓
2 pcs	rear bumper retainer		\$ 18.70		\$ Su 37.40 X
10 pcs	rear bumper clips		\$ 3.50		\$ Nu 35.00 ✓
1 pc	rear end panel				\$ R 341.60 X
1 pc	rear end panel garnish				\$ Su 71.60 X
1 pc	rear space tyre top cover				\$ Su 229.90 X
1 pc	rear space tyre sponge				\$ Su 146.60 X
1 pc	tail gate <i>830.60</i>				\$ Nu 885.80 ✓
1 pc	tail gate lock				\$ R 188.40 X
1 pc	tail gate rubber				\$ Su 92.30 X
1 pc	tail gate outer handle				\$ Nu 112.30 X
1 pc	H emblem				\$ Nu 24.70 X
1 pc	fit emblem				\$ Nu 30.50 ✓
1 pc	tail gate trim				\$ Su 171.30 X
1 pc	rear windscreen moulding				\$ Nu 118.50 ✓
1 pc	rear wiper arm				\$ Nu 58.00 X
1 pc	rear wiper arm cap				\$ CM 12.00 ✓
1 pc	rear wiper blade				\$ Su 43.20 X
1 pc	rear wiper motor				\$ Su 225.00 X
	Less 20%				\$ 3,353.70
					\$ 670.74
					\$ 2,682.96
1 set	rear bumper sensor	S.Nett			\$ Su 280.00 <i>2001a</i>
1 tube	rear windscreen sealant	S.Nett			\$ Su 40.00 X NN
	rear no plate	S.Nett			\$ Su 40.00 X
	To putty & spray paint.				\$ 5501 800.00 ✓
	To remove & refix rear windscreen glass.				\$ 100.00 ✓
	To transfer tail gate fitting.				\$ 80.00 <i>601</i>
	To check rear wiring & water leaking				\$ 30.00 <i>15h</i>
	To anti-rust.				\$ 120.00 <i>301</i>
	Labour charges.				\$ 750.00 <i>5001</i>
TG/VL	TOTAL				\$ 4,922.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: