

Not Authoited
Presurvey B4 paint

83792.85

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9901K

AAD2112-138

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHB9901K

JTDKB3FU203092287

TOYOTA

PRIUS GEN 4

25/12/2021

TOKIO

16/10/2020

28 DEC 2021

	PART
1	COVER, FRONT BUMPER
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER
1	ABSORBER, FRONT BUMPER ENERGY
1	BRACKET, FRONT BUMPER SIDE, LH
1	UNIT ASSY, HEADLAMP, LH
1	LAMP ASSY, FOG, LH
1	GRILLE SUB-ASSY, RADIATOR
1	GRILLE, RADIATOR, LOWER NO.1
1	EMBLEM ASSY, RADIATOR GRILLE
1	MOULDING, FRONT BUMPER SIDE, LH

	LIST
\$	R 521.00 ✓
\$	H 716.60 X
\$	su 80.20 X
\$	D 59.30 ✓
\$	ngem 2,637.60 ✓
\$	su 237.1 X
\$	D 422.50 ✓
\$	CM 178.60 ✓
\$	m 105.80 ✓
\$	cu 95.6 ✓
TOTAL	\$ 5,054.30
15% bumper towing cover mis 30.20 25%	\$ 1,263.58
	\$ 3,790.73

15% bumper towing cover mis 30.20 25%

Special Nett

1	FRT BUMPER CLIP
1	FRT BUMPER RETAINER CLIP
1	FR NUMBER PLATE WITH MOULDING
TOTAL	

\$	na 60.00 50.00
\$	na 65.00 X
\$	by 200.00 45.00
TOTAL	\$ 325.00

TOTAL PARTS \$ 4,115.73

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas. \$

na 240.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. \$

na 380.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9901K**AAD2112-138**

Panel Beating, Knocking And Straightening The Necessary
Portion, Remove And Renewal Of Parts, Adjust And Realign
The Same

\$ 1,600.00

2001

To transfer of rear end panel fittings, attachment to facilitate
bodywork repair.

\$ 380.00

na X

Putty And Spray Painting Of The Affected Portion.

\$ 1,600.00

4401

To reinstall rear bumper parking sensor.

\$ 170.00

na X

To transfer of tire, rim and on wheel balancing.

\$ 170.00

na X

To Check Electrical Lighting Concerned.

\$ 170.00

201

To check steering geometry and computer wheel alignment

\$ 220.00

na X

To remove and refit of rear fender fittings, attachment and

\$ 170.00

na X

TOTAL \$ 5,100.00**Over All Total \$ 9,215.73****(PART-BY-PART) Repair Days**

20 days

9238.38

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: