

Not Authoised  
Recovery B4 paint

**Trans-cab Auto Services Pte Ltd**

**AAD2112-138**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB9901K**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

**SHB9901K**

JTDKB3FU203092287

TOYOTA

PRIUS GEN 4

25/12/2021

**TOKIO**

16/10/2020

- PART**
- 1 COVER, FRONT BUMPER
  - 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
  - 1 ABSORBER, FRONT BUMPER ENERGY
  - 1 BRACKET, FRONT BUMPER SIDE, LH
  - 1 UNIT ASSY, HEADLAMP, LH
  - 1 LAMP ASSY, FOG, LH
  - 1 GRILLE SUB-ASSY, RADIATOR
  - 1 GRILLE, RADIATOR, LOWER NO.1
  - 1 EMBLEM ASSY, RADIATOR GRILLE
  - 1 MOULDING, FRONT BUMPER SIDE, LH

	LIST	
\$	Rz 521.00	✓
\$	R 716.60	X
\$	R 80.20	X
\$	Diy 59.30	✓
\$	M30M 2,637.60	✓
\$	R 237.1	X
\$	Diy 422.50	✓
\$	CM 178.60	✓
\$	M 105.80	✓
\$	W 95.6	✓
<b>TOTAL</b>	<b>\$ 5,054.30</b>	
<b>25%</b>	<b>\$ 1,263.58</b>	
	<b>\$ 3,790.73</b>	

**Special Nett**

- 1 FRT BUMPER CLIP
- 1 FRT BUMPER RETAINER CLIP
- 1 FR NUMBER PLATE WITH MOULDING

**TOTAL**

\$	M 60.00	50M
\$	W 65.00	X
\$	R 200.00	45M
<b>TOTAL</b>	<b>\$ 325.00</b>	

**TOTAL PARTS \$ 4,115.73**

**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ N 240.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ N 380.00 X

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB9901K****AAD2112-138**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	2001
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	nn 380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	4401
To reinstall rear bumper parking sensor.	\$	nn 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To remove and refit of rear fender fittings, attachment and	\$	nn 170.00	X
<b>TOTAL</b>	<b>\$</b>	<b>5,100.00</b>	
<b>Over All Total</b>	<b>\$</b>	<b>9,215.73</b>	

**(PART-BY-PART) Repair Days****20 days****2 days****LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: