

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21013355/BTY3N2**Date:** 18/04/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00068522101

**Claimant Vehicle No :** SJE6243G **Insured Vehicle No :** GBD7315B

Date of Loss: 23/12/2021 Nature of Claim: TP Claim No: SNM21D207561/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJE6243G**

Make & Model: HONDA ODYSSEY, 2.3 (A) Engine No: K24A64001163

Reg. Date: 28/09/2006 (Man. Year: 2006) Chassis No: JHMRB18507C201165

Colour: Silver Odometer: 21303 km

Engine Capacity: 2354 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/40R18 Rear Tyre Size: 235/40R18

Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,538.16	3,297.68	5,240.48	61.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,970.00	1,680.00	2,290.00	57.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,508.16</b>	<b>4,977.68</b>	<b>7,530.48</b>	<b>60.20</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,500.00</b>		
<b>(S\$)</b>	12,508.16	3,500.00	9,008.16	72.02
<b>+ GST 7.00/7.00% (S\$)</b>	875.57	245.00	630.57	72.02
<b>Nett Amount (S\$)</b>	<b>13,383.73</b>	<b>3,745.00</b>	<b>9,638.73</b>	<b>72.02</b>

INSPECTION

Date of Assignment: 11/01/2022

Date Inspected: 31/12/2021 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)  
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit  
Singapore 415875

Estimated Period of Repair: 7.0 days

**Adjuster:** Lim Teow Guan**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 18 Apr 2022)
<b>Parts:</b> M1-MPV	HONDA ODYSSEY 2.3 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJE6243G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH REAR DOOR	Dented	1,372.80 FL	*895.00 FL
2	1		*RH REAR DOOR OUTER HANDLE	Not Necessary	178.30 FL	*- FL
3	1		*RH REAR DOOR LOWER PROTECTOR	Not Necessary	44.70 FL	*- FL
4	1		*RH REAR DOOR FRAME BLACK TAPE	Necessary	58.50 FL	*45.00 FL
5	1		*RH REAR DOOR LOCK	Not Necessary	175.80 FL	*- FL
6	1		*RH REAR DOOR WEATHERSTRIP	Not Necessary	143.80 FL	*- FL
7	1		*RH REAR FENDER	Dented	1,060.70 FL	*988.00 FL
8	1		*RH REAR FENDER LOWER PROTECTOR	Not Damaged	19.20 FL	*- FL
9	1		*RH REAR FENDER GLASS WITH RUBBER MOULDING	Necessary	501.80 FL	*110.00 FL
10	1		*RH REAR FENDER INNER TRIM	Not Damaged	556.80 FL	*- FL
11	1		*REAR BUMPER	Broken	583.60 FL	*583.60 FL
12	1		*REAR BUMPER RH SIDE RETAINER	Necessary	33.20 FL	*33.20 FL
13	1		*RH TAILLAMP ASSY	Not Damaged	22.30 FL	*- FL
14	1		*RH REAR SHOCK ABSORBER	Not Necessary	312.50 FL	*- FL
15	1		*RH REAR KNUCKLE ARM	Not Necessary	426.70 FL	*- FL
16	1		*RH REAR TRAILING ARM	Not Necessary	571.90 FL	*- FL
17	1		*RH REAR UPPER ARM	Not Necessary	192.80 FL	*- FL
18	1		*RH REAR WHEEL BEARING	Jammed	142.30 FL	*142.30 FL
19	1		*SET RH REAR DOOR SUN VISOR	Not Damaged	280.00 FS	*- FS
20	1		*RH SIDE ROCKER PANEL SPOILER	Not Damaged	680.00 FS	*- FS
21	1		*REAR BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
22	1		*REAR BUMPER LOWER SPOILER	Not Damaged	850.00 FS	*- FS
23	1		*RH REAR FENDER GLASS SEALANT	Necessary	70.00 FS	*30.00 FS
24	1		*RH REAR FENDER GLASS INNER SEAL	Necessary	40.00 FS	*20.00 FS
25	1		*RH REAR FENDER JOINT SEALANT	Necessary	70.00 FS	*30.00 FS
26	1		*RH REAR SPORT RIM	Cut	950.00 FS	*950.00 FS
27	1		*RH REAR TYRE	Not Damaged	350.00 FS	*- FS
28	1		*BRAKE FLUID	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>9,817.70</b>	<b>3,857.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	1,279.54	559.42
<b>Total Parts (\$)</b>	<b>8,538.16</b>	<b>3,297.68</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS.TO PANEL BEATING,CUT,WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,200.00	800.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,300.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	80.00	0.00
5	REMOVE AND REPLACE RH REAR DOOR INNER MECHANISM TO NEW DOOR	New	120.00	80.00
6	REMOVE AND REINSTALL ROOF LINING,SEATS,SEAT BELTS,CARPET,TRIM AND BOARDS TO ASSIST REPAIR	New	380.00	0.00
7	REMOVE AND REPLACE RH REAR FENDER GLASS TO ASSIST EPAIR	New	180.00	80.00
8	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	380.00	0.00
9	TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM	New	120.00	60.00
10	RE-BALANCE RH REAR SPORT RIM AND TYRE	New	50.00	0.00
11	REMOVE AND REINSTALL REAR BUMPER REVERSE SENSOR TO ASSIST REPAIR	New	80.00	60.00
			<b>Gross Labour Cost (\$)</b>	<b>3,970.00</b>
				<b>1,680.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >