

BIFROST AUTO PTE LTD
 8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875
 Tel: +65 64524457
 Fax: +65 64524584
 Company Reg No: 201929175W

Estimate

Vehicle No: SJE6243G
 Model and make: Honda Odyssey
 Chassis: JHMRB18507C201165

2006

Qty Spare parts

List price

1	RH rear door	\$	895.00	1,372.80	DDV ✓
1	RH rear door outer handle	\$		178.30	} NNA
1	RH rear door lower protector	\$		44.70	
1	RH rear door frame black tape	\$	45.00	58.50	NECV ✓
1	RH rear door lock	\$		175.80	} NNA
1	RH rear door weatherstrip	\$		143.80	
1	RH rear fender	\$	988.00	1,060.70	DDV ✓
1	RH rear fender lower protector	\$		49.20	NDX
1	RH rear fender glass with rubber moulding	\$	110.00	501.80	NECV ✓
1	RH rear fender inner trim	\$		556.80	NDX
1	Rear bumper	\$		583.60	BRV ✓
1	Rear bumper RH side retainer	\$		33.20	NECV ✓
1	RH taillamp assy	\$		22.30	NDX
1	RH rear shock absorber	\$		312.50	} ? NNA
1	RH rear knuckle arm	\$		426.70	
1	RH rear trailing arm	\$		571.90	
1	RH rear upper arm	\$		192.80	
1	RH rear wheel bearing	\$		142.30	✓ JNV
		\$	2796.80	6,397.70	
		-20% \$	559.36	1,279.54	
		\$	2237.44	5,118.16	

Qty Spare parts

Special nett price

1set	RH rear door sun visor	\$		280.00	NDX
1	RH side rocker panel spoiler	\$		680.00	NDX
1	Rear bumper clips	\$	30.00	70.00	NECV ✓
1	Rear bumper lower spoiler	\$	30.00	850.00	NDX
1	RH rear fender glass sealant	\$	30.00	70.00	NECV ✓
1	RH rear fender glass inner seal	\$	20.00	40.00	NECV ✓
1	RH rear fender joint sealant	\$	30.00	70.00	NECV ✓
1	RH rear sport rim	\$		950.00	WTV ✓
1	RH rear tyre	\$		350.00	NDX
1	Brake fluid	\$		60.00	NNA
			110.00		

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
 To panel beating, cut / weld and re-align all affected panels

\$ 800.00 ~~1,200.00~~ ✓

Spray painting on affected panels

\$ 600.00 ~~1,300.00~~ ✓

Check wiring and lighting system	S	80.00	} NNX
Apply rust coating chemical on affected panels	S	80.00	
Remove and replace RH rear door inner mechanism to new door	S	80.00	120.00 ✓
Remove and reinstall roof lining, seats, seat belts, carpet, trim and boards to assist repair	S		380.00 NNX
Remove and replace RH rear fender glass to assist repair	S	80.00	180.00 ✓
Remove and replace rear undercarriage parts to assist repair	S		380.00 = NNX
Test drive and adjust wheel alignment system	S	60.00	120.00 ✓
Re-balance RH rear sport rim and tyre	S		50.00 NNX
Remove and reinstall rear bumper reverse sensors to assist repair	S	60.00	80.00
	Total: S	1680.00	12,508.16

Survey & RBA survey
 31/12/2021
 13:30 hrs
 TGLim
 M-

Lump sum repair
 Repair days 7

Parts	2237.44
SN	110.00
Labour	1680.00
	<hr/>
	4027.44
@20%	805.49
	<hr/>
	3221.95

LS 3200/2

TGLim Mmi
 8/1/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: