

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21013357/UEA3Q2  
**Date:** 18/04/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210074776
<b>Claimant Vehicle No :</b>	GBE5522C	<b>Insured Vehicle No :</b>	GBG8208E
Date of Loss:	30/12/2021	Nature of Claim:	TP
		Claim No:	2446663250SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBE5522C</b>	Engine No:	1KD2569812
Make & Model:	TOYOTA HIACE, 3.0 (A)	Chassis No:	KDH2010183290
Reg. Date:	08/01/2016 (Man. Year: 2015)	Odometer:	185627 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	6 mm	Rear Left Side:	6 mm
Front Right Side:	6 mm	Rear Right Side:	6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,355.10	1,928.92	3,426.18	63.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	830.00	470.00	36.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,655.10</b>	<b>2,758.92</b>	<b>3,896.18</b>	<b>58.54</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,200.00</b>		
<b>(S\$)</b>	6,655.10	2,200.00	4,455.10	66.94
<b>+ GST 7.00/7.00% (S\$)</b>	465.86	154.00	311.86	66.94
<b>Nett Amount (S\$)</b>	<b>7,120.96</b>	<b>2,354.00</b>	<b>4,766.96</b>	<b>66.94</b>
<b>+ Car Rental (4.0 x S\$85.00/day) (S\$)</b>		340.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,696.00</b>		

**INSPECTION**

Date of Assignment:	31/12/2021		
Date Inspected:	31/12/2021	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	3.0 days		

**Adjuster:** MARCUS CHUA**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

*ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	2,015.20 F	*2,015.20 FL
2	2		*TAILGATE HINGES	Bent / Twisted	170.00 F	*170.00 FL
3	2		*TAILGATE DAMPERS	Not Necessary	560.00 F	*- FL
4	1		*TAILGATE STOPPER N/S	Damaged	93.20 F	*93.20 FL
5	1		*TAILGATE INNER SIDE RUBBER N/S	Twisted	53.50 F	*53.50 FL
6	1		*TAILGATE INNER TOP RAIL PANEL	Repair	885.10 F	*- FL
7	1		*REAR WINDSCREEN	Not Necessary	1,333.10 F	*- FL
8	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
9	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*40.00 FS
10	1		*TAILGATE 70KM/H STICKER	Necessary	20.00 FS	*10.00 FS
11	1		*TAILGATE REAR LOGO	Necessary	45.00 FS	*45.00 FS
12	1		*SET TAILGATE INNER ALUMINIUM REVIT	Necessary	80.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>5,355.10</b>	<b>2,511.90</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$)</b>	0.00	582.98
<b>Total Parts (\$)</b>	<b>5,355.10</b>	<b>1,928.92</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING }	New	50.00	80.00
2	TO DISMANTLE & REFIX TAILGATE MECHANISM }	New	80.00	0.00
3	TO SPRAY RUST PROOFING	New	50.00	30.00
4	TO DISMANTLE & REFIX REAR WINDSCREEN	New	120.00	120.00
5	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	500.00	300.00
6	TO PUTTY & SPRAY PAINTING	New	500.00	300.00
			<b>Gross Labour Cost (\$)</b>	<b>1,300.00</b>
				<b>830.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >