

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: G3E 5522C  
 at Workshop m/s A.  
 of \_\_\_\_\_  
 Insured: G3G 8209E  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: G3E 5522C Yr Regn: 08/01/16  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or car  
 Make: Toyota hiace c.c 2982  
 Colour: white A/C: Insured / Std / NI / NA  
 Sp. Reading: 185627 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: KDH2010183290  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inoper / Jammed / Leaked / Burnt or  
 Brake: Inoper / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Tyre Size: F: 195 R15  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 30/1/17 D.O.I. 31/1/17  
 Survey held at \_\_\_\_\_

Bal. or Market Value: \$ 38k.  
 IDAC Accident Rpt: Consistent? : Yes or No  
 GIA / PR Seen: Consistent? : Yes or No  
 Est. Repairs: 3 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS 940R  
 Date: \_\_\_\_\_ Person Contacted: LTA 617240  
 Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear Tailgate  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Dec 9 9500

5/1/17 have GIA  
2/5 \$ 2200 informed Alan.

Date/Time, File Pass to?  : Preli. Report  : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_  
 Report Format : \_\_\_\_\_  
 Lump Sum / I.B.I: (\$) \_\_\_\_\_ )  
 Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_  
 Add Fee:  : Site Insp (\$) \_\_\_\_\_ )  
 : Interview (\$) \_\_\_\_\_ )  
 : Tech. Invs (\$) \_\_\_\_\_ )  
 : Weekend (\$) \_\_\_\_\_ )  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 ) S + RS, SI \_\_\_\_\_  
 ) Photos \_\_\_\_\_  
 ) Others \_\_\_\_\_  
 TOTAL \_\_\_\_\_

: Ashu

FASTECH AUTO PTE LTD  
1 Kaki Bukit Ave 6 #01-48 Autobay  
Singapore 417883  
Tel No: 67452063/ 67467158 Fax No: 67458520  
Tax Reg No : 200006262D

not approved  
date  
31/12/21  
1/5 @ 2200/  
3 days

VEHICLE No: GBE 5522C

1PC TAILGATE  
2PCS TAILGATE HINGES @\$85.00  
2PCS TAILGATE DAMPERS @\$280.00  
1PC TAILGATE STOPPER N/S  
1PC TAILGATE INNER SIDE RUBBER N/S  
1PC TAILGATE INNER TOP RAIL PANEL  
1PC REAR WINDSCREEN

Body 20 \$2,015.20 ✓  
Bent / rml \$170.00 ✓  
r1 \$560.00 X  
Damped \$93.20 ✓  
rml \$53.50 ✓  
R \$885.10 X  
r1 \$1,333.10 X  
\$5,110.10

S.NETT

1PC REAR WINDSCREEN SEALANT  
1PC REAR WINDSCREEN INNER SEAL  
1PC TAILGATE 70km/h STICKER  
1PC TAILGATE REAR LOGO  
1SET TAILGATE INNER ALUMINIUM REVIT

rll \$50.00 40  
rll \$50.00 40  
rll \$20.00 10  
rll \$45.00 ✓  
rll \$80.00 45

TO CHECK WIRING  
TO DISMANTLE & REFIX TAILGATE MECHANISM  
TO SPRAY RUST PROOFING  
TO DISMANTLE & REFIX REAR WINDSCREEN  
LABOUR FOR PANEL BEATING & REPLACED PARTS  
TO PUTTY & SPRAY PAINTING

\$50.00 280  
\$80.00 30  
\$50.00 30  
\$120.00 ✓  
\$500.00 300  
\$500.00 300  
TOTAL \$6,655.10

LKK Auto Consultants hence notify the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company  
Acknowledged by Repairer  
Signature:  
Date:

p-2331.90  
252  
p-1748.92  
SN-180  
L-830  
2758.92  
20%  
2207.13