

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21013359/GTY3E2

**Date:** 10/06/2022

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00102062100  
Claimant Vehicle No: BARRIER Insured Vehicle No: SKW3832U  
Date of Loss: 17/12/2021 Nature of Claim: TP Claim No: SNM21D207572/C02/IRENE

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: BARRIER  
Make & Model: ADIVA AD1 200, 190cc 3W Engine No: HIDDEN  
Reg. Date: (Man. Year: ) Chassis No: HIDDEN  
Colour: Others Odometer: 0 km  
Engine Capacity: 0 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: Rear Tyre Size:  
Front Left Side: 0 mm Rear Left Side: 0 mm  
Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	850.00	637.50	212.50	25.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	250.00	250.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,100.00</b>	<b>887.50</b>	<b>212.50</b>	<b>19.32</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>77.00</b>	<b>62.13</b>	<b>14.87</b>	<b>19.31</b>
<b>Nett Amount (S\$)</b>	<b>1,177.00</b>	<b>949.63</b>	<b>227.37</b>	<b>19.32</b>

### INSPECTION

Date of Assignment: 07/06/2022  
Date Inspected: 30/12/2021 Inspected At: No. 1 Rocher Canal Road #B2-01  
Singapore 188504  
Repairer: Wei Long Electronics Engineering (HQ)  
Estimated Period of Repair: 1.0 days

**Adjuster:** XING GUO QIANG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 10 Jun 2022)	
<b>Parts:</b>	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for BARRIER)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*1.5M BY 2.5M FOLDING BARRIER ARM AT BENCOOLEN EXIT	Broken	850.00 F	*850.00 FL	
F=Franchise part. L=ListItemDisc.							
					<b>Sub Total (\$)</b>	<b>850.00</b>	<b>850.00</b>
					<b>- List Item Discount on L Items 0.00/25.00% (\$)</b>	0.00	212.50
					<b>Total Parts (\$)</b>	<b>850.00</b>	<b>637.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	DELIVERY AND INSTALLATION	New	250.00	250.00
			<b>Gross Labour Cost (\$)</b>	<b>250.00</b>
				<b>250.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >