



Lim Cecilia

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave #01-48 Autobay  
Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

2/17/21

3/1/21

2/59 9250 / limited  
11 days

VEHICLE No: SCW 30G

1PC	BOOTLID	875.00	Bent/Suc	\$950.00	—
1PC	BOOTLID REAR LOGO	38.00	neu	\$105.00	—
1PC	BOOTLID '2.4' EMBLEM		neu	\$45.00	—
1PC	BOOTLID 'ACCORD' EMBLEM	50	neu	\$65.00	—
2PCS	BOOTLID OUTER GARNISH		R	\$685.00	X
1PC	BOOTLID INNER LOCK		Suc	\$266.00	X
1SET	TAILGATE INNER TRIM BOARD CLIPS		17	\$50.00	X
1PC	REAR BUMPER	845.20	D.S	\$1,850.00	—
2PCS	REAR BUMPER SIDE HOLDERS @\$165.00	35x2=70	neu	\$330.00	—
1PC	REAR BUMPER REINFORCEMENT	345.20	D.S	\$915.00	—
1PC	REAR BUMPER LOWER SPOILER		D.S	\$680.00	—
1SET	REAR BUMPER CLIPS	30.00	neu	\$50.00	—
2PCS	TAILLAMPS @\$650.00	425x2=850	CRU	\$1,300.00	—
1PC	REAR END PANEL	366.20	Body ID	\$620.00	—
1PC	REAR END PANEL TOP GARNISH	162.50	neu	\$350.00	—
1PC	REAR FLOOR PANEL		R	\$1,120.00	X
1PC	REAR FLOOR PANEL TOP BOARD	425	Torn	\$540.00	—
1PC	BONNET	1145.20	Suc	\$1,410.00	—
1PC	BONNET INSULATOR		17	\$234.00	X
1PC	BONNET LOCK	166.	neu	\$190.00	—
1PC	FRONT BUMPER	857.20	D.S	\$1,820.00	—
1PC	FRONT BUMPER LOGO	38.00	neu	\$105.00	—
2PCS	FRONT BUMPER SIDE RETAINERS @\$145.00	35x2=70	Bent	\$290.00	—
4PCS	FRONT BUMPER PDC SENSORS @\$250.00		Torn	\$1,000.00	200 S/P
1PC	FRONT BUMPER LICENCE PLATE HOLDER	66.80	D.S	\$390.00	—
1PC	FRONT BUMPER CENTRE LOWER GRILLE	94.50	Torn	\$320.00	—
2PCS	FRONT BUMPER FOG LAMPS @\$480.00	285 m/s n	D/S 20	\$960.00	1PC
2PCS	FRONT BUMPER FOG LAMP GARNISHS @\$180.00		NF	\$360.00	X
1PC	FRONT BUMPER REINFORCEMENT	485.20	Bent	\$920.00	—
2PCS	FRONT BUMPER REINFORCEMENT BRACKETS @\$255.00		NS	\$510.00	X
1PC	FRONT BUMPER LOWER REINFORCEMENT		NS	\$450.00	X
1PC	FRONT BUMPER TOP CENTRE GRILLE	166	D.S	\$280.00	—
1PC	FRONT BUMPER TOP RUBBER	48.00	Torn	\$80.00	—
1PC	FRONT BUMPER TOW COVER	20	Torn	\$30.00	—
1SET	FRONT BUMPER CLIPS	30.00	neu	\$50.00	—
2PCS	FRONT BUMPER FOG LAMPS @\$350.00		Repair	\$700.00	X
2PCS	FRONT GRILLE OUTER @\$190.00		CRU	\$380.00	1PC
2PCS	FRONT GRILLE INNER @\$180.00		CRU	\$360.00	1PC
2PCS	HEADLAMPS @\$21200.00	685x2=1370	holder	\$2,400.00	—
1PC	FRONT SUPPORT PANEL	584.00	Suc	\$615.00	—
1PC	FRONT SUPPORT PANEL TOP GARNISH	182.00	D.S	\$218.00	—

(502)

10754

1PC	FRONT AIR DUCT GARNISH	86.20	9.5	\$255.00	/
1PC	AIR CON CONDENSER	962	7.5	\$1,100.00	/
1PC	AIR CON CONDENSER FAN ASSY	450	CRG/GR	\$455.00	/
1PC	RADIATOR	1180	CRG/GR	\$1,280.00	/
1PC	RADIATOR FAN ASSY	450	CRG/GR	\$480.00	/
2PCS	FRONT FENDERS @\$ 650.00	482 x 2 = 964.00	GR/GR	\$1,300.00	/
2PCS	FRONT FENDER INNERSHIELDS @\$148.30	502	GR/GR	\$296.60	X
1PC	HORN UNIT	82.00	17	\$99.00	/
				<b>\$29,258.60</b>	

S.NETT

1SET	REAR FLOOR PANEL INSULATOR		ALL	\$250.00	100
1PC	REAR LICENCE PLATE		11	\$50.00	X
1PC	REAR END PANEL SEALANT		ALL	\$50.00	/
1PC	FRONT LICENCE PLATE		GR/GR	\$50.00	40
1BOL	RADIATOR COOLANT		ALL	\$50.00	20
1BOL	AIR CON OIL		ALL	\$50.00	20

TO CHECK WIRING	\$50.00	30
TO DISMANTLE & REPLACED REAR PDC SENSOR	\$100.00	50
TO DISMANTLE & REFIX REAR WINDSCREEN	11	\$150.00 X
TO TRANSFER BOOTLID MECHANISM	\$100.00	60
TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	11	\$100.00 X
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$150.00	80
TO DISMANTLE & REPLACED REAR EXHAUST	11	\$180.00 X
TO REFILL AIR CON GAS	\$120.00	100
TO MOUNT VEHICLE ON CAR O-LINER	11	\$380.00 X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$3,000.00	1500
TO PUTTY & SPRAY PAINTING	\$2,800.00	1800
<b>TOTAL</b>	<b>\$36,888.60</b>	

LKK Auto Consultants hereby notify the Repairer of the following:

- To re-survey before and after spray painting
- To display damaged part(s) during re-survey
- Parts prices are subject to confirmation
- Third party survey in or a "Without Prejudice" form
- No legal proceedings is allowed
- Supplementary items must be re-surveyed and is subject to final approval from Insurer's Company

Acknowledged by Repairer  
Signature  
Date

14928-20  
502  
P-7464.1  
S.W-430  
L-3620  
11/14/1