

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG22000001/AEA3Q2**Date:** 09/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800089337
Claimant Vehicle No :	SJX5652R	Insured Vehicle No :	SDT8005G
Date of Loss:	30/12/2021	Nature of Claim:	TP
		Claim No:	7362660304SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX5652R	Engine No:	L310495516
Make & Model:	MAZDA 8, 2.3 (A)	Chassis No:	JM6LY103200200654
Reg. Date:	25/06/2010 (Man. Year: 2010)	Odometer:	129675 km
Colour:	Blue		
Engine Capacity:	2261 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,165.84	3,764.24	14,401.60	79.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,800.00	2,070.00	5,730.00	73.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,965.84	5,834.24	20,131.60	77.53
Approved Total (Overridden) (S\$)		4,600.00		
Nett Amount (S\$)	25,965.84	4,600.00	21,365.84	82.28
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	31/12/2021	
Date Inspected:	31/12/2021	Inspected At: HD Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Distorted	383.20 FL	*383.20 FL
2	1		*FRONT FENDER QUARTER GARNISH RH	Not Necessary	83.00 FL	*- FL
3	1		*FRONT FENDER INNER SPONGE RH	Not Necessary	94.60 FL	*- FL
4	1		*FRONT FENDER COWLING RH	Torn	114.30 FL	*114.30 FL
5	1		*FRONT WINDSCREEN MOULDING	Not Necessary	176.40 FL	*- FL
6	1		*FRONT SAFETY BELT RH	Not Necessary	1,588.90 FL	*- FL
7	1		*FRONT DOOR PILLAR RH (OUTER)	Repair	1,070.60 FL	*- FL
8	1		*FRONT DOOR RH	Dented	1,796.40 FL	*1,620.00 FL
9	1		*FRONT SIDE MIRROR RH	Not Necessary	1,368.00 FL	*- FL
10	1		*FRONT DOOR OUTER HANDLE RH	Not Necessary	224.00 FL	*- FL
11	2		*FRONT DOOR HINGE RH	Bent	103.40 FL	*103.40 FL
12	1		*FRONT DOOR CHECKER RH	Damaged	126.40 FL	*126.40 FL
13	1		*FRONT DOOR FRAME STEP GARNISH RH	Not Necessary	149.80 FL	*- FL
14	1		*FRONT DOOR SPEAKER RH	Not Necessary	398.60 FL	*- FL
15	1		*FRONT DOOR WIRE HARNESS RH	Not Necessary	928.50 FL	*- FL
16	1		*FRONT DOOR INNER TRIM RH	Cracked	1,216.70 FL	*758.00 FL
17	1		*FRONT DOOR INNER LOCK RH	Not Necessary	367.10 FL	*- FL
18	1		*FRONT DOOR LOCK CATCHER RH	Not Necessary	28.20 FL	*- FL
19	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	114.70 FL	*- FL
20	1		*FRONT DOOR OUTER STEP RH	Not Necessary	142.60 FL	*- FL
21	1		*FRONT DOOR POWER WINDOW MOTOR RH	Not Necessary	379.40 FL	*- FL
22	1		*FRONT DOOR REGULATOR RH	Not Necessary	198.70 FL	*- FL
23	1		*FRONT DOOR GLASS CHANNEL RH	Not Necessary	83.40 FL	*- FL
24	1		*FRONT DOOR FRAME WEATHER STRIP RH	Not Necessary	159.90 FL	*- FL
25	1		*ROCKER PANEL RH (OUTER)	Repair	979.60 FL	*- FL
26	1		*SIDE SKIRT RH	Deformed	875.00 FL	*875.00 FL
27	1		*FRONT STEERING RACK AND PINION	Not Necessary	1,867.00 FL	*- FL
28	1		*FRONT LOWER ARM RH	Not Necessary	289.30 FL	*- FL
29	1		*FRONT SWING ARM RH	Not Necessary	529.60 FL	*- FL
30	1		*FRONT SHOCK ABSORBER RH	Not Necessary	298.60 FL	*- FL
31	1		*FRONT LINKAGE RH	Not Necessary	101.20 FL	*- FL
32	1		*FRONT WHEEL HUP RH	Not Necessary	480.40 FL	*- FL
33	1		*FRONT WHEEL HUP BEARING RH	Not Necessary	299.50 FL	*- FL
34	1		*FRONT KNUCKLE ARM RH	Not Necessary	631.10 FL	*- FL
35	1		*FRONT ABS SENSOR RH	Not Necessary	296.70 FL	*- FL
36	1		*FRONT FENDER COWLING CLIP RH	Necessary	50.00 FS	*30.00 FS
37	1		*FRONT WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
38	1		*FRONT WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
39	1		*FRONT DOOR PILLAR (OUTER) SEALANT RH	Not Necessary	120.00 FS	*- FS
40	1		*SET FRONT PILLAR INNER GARNISH CLIP	Not Necessary	40.00 FS	*- FS
41	1		*FRONT DOOR SOUND PROOF RH (SPECIAL TYPE)	Not Necessary	750.00 FS	*- FS
42	1		*SET FRONT WIPER GARNISH CLIP	Not Necessary	80.00 FS	*- FS
43	1		*FRONT WHEEL TYRE RH	Not Necessary	800.00 FS	*- FS
44	1		*FRONT WHEEL RIM RH	Cut	1,800.00 FS	*550.00 FS
45	1		*BRAKE OIL	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	21,754.80	4,560.30
- List Item Discount on L Items 20.00/20.00% (\$)	3,588.96	796.06
Total Parts (\$)	18,165.84	3,764.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	2,200.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	800.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	250.00	30.00
5	REMOVE & REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	0.00
6	REMOVE AND REFIX FRONT DASHBOARD	New	1,200.00	0.00
7	REMOVE AND REFIX SAFETY BELT	New	250.00	0.00
8	TRANFER FRONT DOOR MECHANISM	New	80.00	80.00
9	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	650.00	220.00
10	FOUR WHEEL ALIGNMENT	New	120.00	80.00
11	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
12	RESET ABS LIGHT	New	350.00	0.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGMENT /CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			7,800.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >