

Company Reg No: 202136904Z

Tel : 6341 6789 Fax: 6341 6778
E-mail:hdperfectautowork@gmail.com



DATE : 30.12.2021

JMGLY103200200654
Ashes.

CLAIM DETAIL : PARTS

CLAIM DETAIL - PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT FENDER RH <i>Distorted</i>	1	\$ 383.20	\$ 383.20
2	FRONT FENDER QUARTER GARNISH RH <i>M</i>	1	\$ 83.00	\$ 83.00
3	FRONT FENDER INNER SPONGE RH <i>New</i>	1	\$ 94.60	\$ 94.60
4	FRONT FENDER COWLING RH <i>torn</i>	1	\$ 114.30	\$ 114.30
5	FRONT WINDSCREEN MOULDING <i>Not nec</i>	1	\$ 176.40	\$ 176.40
6	FRONT SAFETY BELT RH <i>New</i>	1	\$ 1,588.90	\$ 1,588.90
7	FRONT DOOR PILLAR RH (OUTER) <i>Regis</i>	1	\$ 1,070.60	\$ 1,070.60
8	FRONT DOOR RH <i>Dented</i>	1	\$ 1,796.40	\$ 1,796.40
9	FRONT SIDE MIRROR RH <i>New</i>	1	\$ 1,368.00	\$ 1,368.00
10	FRONT DOOR OUTER HANDLE RH <i>New</i>	1	\$ 224.00	\$ 224.00
11	FRONT DOOR HINGE RH <i>Best.</i>	2	\$ 51.70	\$ 103.40
12	FRONT DOOR CHECKER RH <i>Regd.</i>	1	\$ 126.40	\$ 126.40
13	FRONT DOOR FRAME STEP GARNISH RH <i>New</i>	1	\$ 149.80	\$ 149.80
14	FRONT DOOR SPEAKER RH <i>2nd</i>	1	\$ 398.60	\$ 398.60
15	FRONT DOOR WIRE HARNESS RH <i>1st</i>	1	\$ 928.50	\$ 928.50
16	FRONT DOOR INNER TRIM RH <i>Cracked</i>	1	\$ 1,216.70	\$ 1,216.70
17	FRONT DOOR INNER LOCK RH <i>New</i>	1	\$ 367.10	\$ 367.10
18	FRONT DOOR LOCK CATCHER RH <i>New</i>	1	\$ 28.20	\$ 28.20
19	FRONT DOOR WEATHER STRIP RH Not nec	1	\$ 114.70	\$ 114.70
20	FRONT DOOR OUTER STRIP RH <i>New</i>	1	\$ 142.60	\$ 142.60
21	FRONT DOOR POWER WINDOW MOTOR RH <i>2nd</i>	1	\$ 379.40	\$ 379.40
22	FRONT DOOR REGULATOR RH <i>1st</i>	1	\$ 198.70	\$ 198.70
23	FRONT DOOR GLASS CHANNEL RH <i>New</i>	1	\$ 83.40	\$ 83.40
24	FRONT DOOR FRAME WEATHER STRIP RH <i>New</i>	1	\$ 159.90	\$ 159.90
25	ROCKER PANEL RH (OUTER) <i>Regis</i>	1	\$ 979.60	\$ 979.60
26	SIDE SKIRT RH <i>Deland</i>	1	\$ 875.00	\$ 875.00

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SJX5652R**
 MODEL : **MAZDA 8**
 DATE OF ACCIDENT : 30.12.2021
 TIME OF ACCIDENT : 14:50HRS

27	FRONT STEERING RACK AND PINION <i>new</i>	1	\$ 1,867.00	\$ 1,867.00	<i>+</i>
28	FRONT LOWER ARM RH <i>new</i>	1	\$ 289.30	\$ 289.30	<i>+</i>
29	FRONT SWING ARM RH <i>new</i>	1	\$ 529.60	\$ 529.60	<i>+</i>
30	FRONT SHOCK ABSORBER RH <i>new</i>	1	\$ 298.60	\$ 298.60	<i>+</i>
31	FRONT LINKAGE RH <i>new</i>	1	\$ 101.20	\$ 101.20	<i>+</i>
32	FRONT WHEEL HUP RH <i>new</i>	1	\$ 480.40	\$ 480.40	<i>+</i>
33	FRONT WHEEL HUP BEARING RH <i>new</i>	1	\$ 299.50	\$ 299.50	<i>+</i>
34	FRONT KNUCKLE ARM RH <i>new</i>	1	\$ 631.10	\$ 631.10	<i>+</i>
35	FRONT ABS SENSOR RH <i>new</i>	1	\$ 296.70	\$ 296.70	<i>+</i>

3980.30

TOTAL PRICE \$ 17,944.80

3184.24

LESS 20% \$ 3,588.96

SUB TOTAL PRICE \$ 14,355.84

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT FENDER COWLING CLIP RH <i>new</i>	1	\$ 50.00	\$ 50.00	<i>30</i>
2	FRONT WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
3	FRONT WINDSCREEN INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
4	FRONT DOOR PILLAR (OUTER) SEALANT RH <i>new</i>	1	\$ 120.00	\$ 120.00	<i>+</i>
5	FRONT PILLAR INNER GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	<i>+</i>
6	FRONT DOOR SOUND PROOF RH (SPECIAL TYPE) <i>new</i>	1	\$ 750.00	\$ 750.00	<i>+</i>
7	FRONT WIPER GARNISH CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
8	FRONT WHEEL TYRE RH <i>new</i>	1	\$ 800.00	\$ 800.00	<i>+</i>
9	FRONT WHEEL RIM RH <i>lot</i>	1	\$ 1,800.00	\$ 1,800.00	<i>550</i>
10	BRAKE OIL <i>new</i>	1	\$ 30.00	\$ 30.00	<i>+</i>

580

TOTAL \$ 3,810.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,200.00	<i>800</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	<i>800</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	WIRING CHECK	\$ 250.00	<i>30</i>
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	<i>x</i>

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SJX5652R**
 MODEL : **MAZDA 8**
 DATE OF ACCIDENT : 30.12.2021
 TIME OF ACCIDENT : 14:50HRS

6	REMOVE AND REFIX FRONT DASHBOARD	\$ 1,200.00	X
7	REMOVE AND REFIX SAFETY BELT	\$ 250.00	X
8	TRANFER FRONT DOOR MECHANISM	\$ 80.00	✓
9	REMOVE AND REFIX REAR ^{Front} UNDERCARRIAGE	\$ 650.00	220
10	FOUR WHEEL ALIGNMNET	\$ 120.00	80
11	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
12	RESET ABS LIGHT	\$ 350.00	X
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

2070

TOTAL \$7,800.00

TOTAL PARTS COST : \$ 18,165.84
 TOTAL LABOUR COST : \$ 7,800.00
 TOTAL REPAIR COST : \$ 25,965.84

Adrian
 H/S 31/12/21

06 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

total: 5834.24

H/S: A.6K. ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: