

TP111
Justin.

SGV2118H. 2021 March.
Porsche Cayenne. 2985 cc

WP1ZZZ9YZMDA92408.

Front Bumper	Deformed	2436	✓
Front Bumper Clips.	new	30(SN)	✓
Front Bumper Side Holder RH	new	185	X
Front Bumper Lower Garnish.	new	851	X
Front Bumper Sensor	new	285	X
Front Bumper Lower Side Grille RH.	new	398	X
Front Bumper Upper Side Moulding	new	218	✓
Front RH Fender Wheel Arc Garnish.	new	588	✓
Front RH Fender Wheel Arc Garnish Clips.	new	30(SN)	✓
Front RH Fender Inner Shield	torn	385	✓
Front RH Fender Inner Shield clips.	new	30(SN)	✓
Headlamp RH.	cracked	3895	✓

7522

S.N: 110

676980

SGV2118H.

Panel Beating

~~605~~ 500

Spry Painting.

~~602~~ 500

1240

~~50~~ 30

Wiring

To perform diagnostic test.

~~200~~ 150

To remove front bumper sensor

~~100~~ 60

total: 8119.80

H/S : 6.5K

03 Days.

(6.5K)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: