



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : HR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV11833/KEE POH KWANG (JI BAOGUANG)
	Reg No/Reg Date	SMR4949M / 10/01/202
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5051764
	Engine No	G4FGKH748032
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
LAX00000	Credit	31/12/2021/ 11:17	BLE	261 / Edwin Caina	44934	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FR BUMPER, FR SUPPORT, BONNET, LHF FENDER & RHF FENDER REPAIR LHF / RHF A PILLAR, LHF DOOR & RHF DOOR			2	2000		4000.00
E PNT98000 RESPRAY FR BUMPER, BONNET, LHF FENDER, RHF FENDER LHF A PILLAR, RHF A PILLAR, LHF DOOR & RHF DOOR			2	1400		2800.00
E PNT88000 REMOVE & REFIT AC COND & RADIATOR ASSY						100.00
M SUNDRY TOP UP AC GAS						80.00
A 54900099 REMOVE & REFIT DASHBOARD ASSY, GLOVE COMPARTMENT, CENTRE CONSOLE & INSTRUMENT PNL			4	200		800.00
A 54900099 RENEW DRIVER AIRBAG, PASSENGER AIRBAG, AIRBAG CONTROL UNIT & AIRBAG FR SENSOR			4	200		800.00
A 54900099 RENEW DRIVER SEATBELT, FR PASSENGER SEATBELT & SEATBELT CATCH			2	200		400.00
A 54900099 RENEW FR INTAKE MANIFOLD			Xm 200?			400.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM			30			80.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM						120.00
E PNT88000 CONDUCT CHASSIS ALIGNMENT - CELETTE BENCH			500			1000.00
WHEEL ALIGNMENT To Conduct Computerize Full Wheel Alignment			?			120.00
E PNT88000 RENEW FR WINDSCREEN GLASS						240.00
SUNDRY INSTALL FR WINDSCREEN SOLAR FILM @side agent						280.00
SUNDRY						80.00

Estimate

confirm & accepted by

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV11833/KEE POH KWANG (JI BAOGUANG)
	Reg No/Reg Date	SMR4949M / 10/01/202
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5051764
	Engine No	G4FGKH748032
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	31/12/2021/ 11:17	BLE	261 / Edwin Caina	44934
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
SUPPLY WINDSCREEN SEALANT					
M SUNDRY					50.00
SUPPLY FR NUMBER PLATE WITH CASING					60 80.00
M SUNDRY					40 80.00
APPLY ANTI CORROSION ON AFFECTED AREAS					
M SUNDRY					
SUPPLY BODY PNL SEALANT					
M SUNDRY					30.00
Sundries					
M COVER-FR BUMPER turn		1.00	633.00	20.00	506.40
M CAP-FRONT HOOK		1.00	9.00	20.00	7.20
M GRILLE-FRONT BUMPER		1.00	262.00	20.00	209.60
M COVER-FR BUMPER FOG LAMP, LH		1.00	15.00	20.00	12.00
M COVER-FR BUMPER FOG LAMP, RH		1.00	15.00	20.00	12.00
M GRILLE ASSY-RADIATOR		1.00	328.00	20.00	262.40
M GARNISH-RADIATOR GRILLE		1.00	38.00	20.00	30.40
M LAMP ASSY-FRONT FOG, LH		1.00	303.00	20.00	242.40
M LAMP ASSY-FRONT FOG, RH		1.00	303.00	20.00	242.40
M MOULDING-FRONT BUMPER, LH		1.00	36.00	20.00	28.80
M MOULDING-FRONT BUMPER, RH		1.00	36.00	20.00	28.80
M LAMP ASSY-SIDE REPEATER, RH		1.00	143.00	20.00	114.40
M LAMP ASSY-SIDE REPEATER, LH		1.00	143.00	20.00	114.40
M AIR DUCT-FR BUMPER, LH		1.00	14.00	20.00	11.20
M AIR DUCT-FR BUMPER, RH		1.00	14.00	20.00	11.20
M ABSORBER-FRONT BUMPER ENERGY		1.00	84.00	20.00	67.20
M STIFFNER-FR BPR LWR		1.00	114.00	20.00	91.20
M BRACKET-FR BUMPER UPR SIDE MTG		1.00	22.00	20.00	17.60
M BRACKET-FR BUMPER UPR SIDE MTG		1.00	22.00	20.00	17.60
M ORNAMENT-KIA NO.115		1.00	32.00	20.00	25.60
M BEAM COMPLETE-FR BUMPER		1.00	497.00	20.00	397.60
M CARRIER ASSY-FRONT END MODULE		1.00	675.00	20.00	540.00
M PANEL ASSY-HOOD		1.00	1502.00	20.00	1201.60
M HINGE ASSY-HOOD, LH		1.00	43.00	20.00	34.40

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	<tr> <td>Cust No/Name</td><td>LCV11833/KEE POH KWANG (JI BAOGUANG)</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMR4949M / 10/01/202</td></tr> <tr> <td>Date In/Mileage</td><td>/ 0</td></tr> <tr> <td>Chassis No</td><td>KNAF3416MK5051764</td></tr> <tr> <td>Engine No</td><td>G4FGKH748032</td></tr> <tr> <td>Make/Model</td><td>KIA/CERATO 1.6 A EX G333</td></tr> <tr> <td>Colour/Trim</td><td>ABT PLATINUM GRAPHI/ WK SATURN BLACK</td></tr>	Cust No/Name	LCV11833/KEE POH KWANG (JI BAOGUANG)	Reg No/Reg Date	SMR4949M / 10/01/202	Date In/Mileage	/ 0	Chassis No	KNAF3416MK5051764	Engine No	G4FGKH748032	Make/Model	KIA/CERATO 1.6 A EX G333	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK
Cust No/Name	LCV11833/KEE POH KWANG (JI BAOGUANG)														
Reg No/Reg Date	SMR4949M / 10/01/202														
Date In/Mileage	/ 0														
Chassis No	KNAF3416MK5051764														
Engine No	G4FGKH748032														
Make/Model	KIA/CERATO 1.6 A EX G333														
Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	31/12/2021/ 11:17	BLE	261 / Edwin Caina	44934
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M HINGE ASSY-HOOD, RH <i>bt</i>		1.00	43.00	20.00	34.40
M PAD-HOOD INSULATING <i>de</i>		1.00	156.00	20.00	124.80
M CLIP-HOOD INSULATING-PAD MTG <i>an</i>		13.00	1.00	20.00	10.40
M LATCH ASSY-HOOD <i>bt</i>		1.00	103.00	20.00	82.40
M LAMP ASSY-HEAD, LH <i>cm</i>		1.00	1219.00	20.00	975.20
M LAMP ASSY-HEAD, RH <i>cm</i>		1.00	1219.00	20.00	975.20
M PANEL-FENDER, LH <i>bt</i>		1.00	430.00	20.00	344.00
M PANEL-FENDER, RH <i>report bu</i>		1.00	430.00	20.00	344.00
M GUARD ASSY-FRONT WHEEL, LH <i>? Xan</i>		1.00	95.00	20.00	76.00
M GUARD ASSY-FRONT WHEEL, RH <i>cm</i>		1.00	95.00	20.00	76.00
M RESERVOIR & PUMP ASSY-WASHER <i>? cm</i>		1.00	146.00	20.00	116.80
M DUCT-EXTENSION <i>? cm</i>		1.00	5.00	20.00	4.00
M SHIELD-AIR INTAKE <i>? Xan</i>		1.00	9.00	20.00	7.20
M DUCT ASSY-AIR <i>? Xan</i>		1.00	55.00	20.00	44.00
M CLEANER ASSY-AIR <i>cm</i>		1.00	174.00	20.00	139.20
M PANEL ASSY-UNDER COVER <i>cm</i>		1.00	117.00	20.00	93.60
M CONDENSER ASSY-COOLER <i>bt</i>		1.00	687.00	20.00	549.60
M GUARD-AIR, LH <i>sc</i>		1.00	28.00	20.00	22.40
M GUARD-AIR, RH <i>sc</i>		1.00	28.00	20.00	22.40
M RADIATOR ASSY <i>bt</i>		1.00	646.00	20.00	516.80
M BLOWER ASSY <i>? cm</i>		1.00	656.00	20.00	524.80
M FILLER NECK ASSY-RADIATOR <i>cm</i>		1.00	28.00	20.00	22.40
M MANIFOLD ASSY-INTAKE <i>? Xan</i>		1.00	906.00	20.00	724.80
M MOULDING-WINDSHIELD GLASS <i>cm</i>		1.00	56.00	20.00	44.80
M COVER ASSY-COWL TOP <i>? cm</i>		1.00	247.00	20.00	197.60
M COVER-AFTER SERVICE, LH <i>? Xan</i>		1.00	11.00	20.00	8.80
M COVER-AFTER SERVICE, RH <i>? Xan</i>		1.00	11.00	20.00	8.80
M S/BELT ASSY-FR LH <i>ACT</i>		1.00	315.00	20.00	252.00
M S/BELT ASSY-FR RH <i>ACT</i>		1.00	317.00	20.00	253.60
M BUCKLE ASSY-FR S/BELT, LH <i>Xm</i>		1.00	179.00	20.00	143.20
M BUCKLE ASSY-FR S/BELT, RH <i>Xm</i>		1.00	114.00	20.00	91.20
M CRASH PAD ASSY-MAIN <i>? ACT</i>		1.00	1279.00	20.00	1023.20
M AIR BAG ASSY-PASSENGER <i>ACT</i>		1.00	1275.00	20.00	1020.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV11833/KEE POH KWANG (JI BAOGUANG)
	Reg No/Reg Date	SMR4949M / 10/01/202
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5051764
	Engine No	G4FGKH748032
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	31/12/2021/ 11:17	BLE	261 / Edwin Caina	44934
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M	MODULE ASSY-STRG WHEEL AIR BAG	1.00	922.00	20.00	737.60
M	CONTACT ASSY-CLOCK SPRING	1.00	253.00	20.00	202.40
M	SENSOR ASSY-A TYPE CRASH	2.00	54.00	20.00	86.40
M	MODULE ASSY-AIR BAG CONTROL	1.00	1025.00	20.00	820.00
M	BRACKET, IU ADHESIVE	1.00	26.00	00.00	26.00
M	COOLANT (4L)	1.00	26.00	23.00	20.02

Estimate

SURVEYOR NAME: RASUL - 4990010068SURVEYOR SIGNATURE: [Signature]DATE: 03/01/22 @ 1500REMARKS: 12 days + 3 = 15 daysEXCESS: TBA / REVERTResin before paint

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

Nett	26,532.42
7% GST on	1857.27
Total Payable	28,389.69

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.