

ASS. REC. BY:

REF:

Smo/ 220000051KV

NAETH

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

um Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SFF 2500H

Yr Regn:

04, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

c.c.

1496

Colour

m. Red

A/C:

Insured / Std / Nil / NA

Sp. Reading

158973

T/Radio:

Insured / Std / Nil / NA

Eng/No:

C/No:

RUI

1207392

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / STD / STD A/Rim or

Tyre Size:

F:

225/50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

Rear

R/Bal.

6

mm

R/Bal.

7

mm

L/Bal.

6

mm

L/Bal.

7

mm

D.O.A.

28/12/21

D.O.I.

4/1/2022

Survey held at

Des. of Damages: ☒ Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

) \$ + RS. SI

) FURTHER

) OTHERS

TOTAL

ort Format :

p Sum / I.B.I: (\$

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

*Not Authored**Penny Bypain**5 days***ESTIMATE**

Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05-01/06, Singapore Land Tower,
Singapore 048623
Attn: Accident Claims Department

Date : 28.12.2021
Vehicle No : SFF2500H
Veh Make/Model : Honda Vezel 1.5X CVT
YOM : 2016
Chassis No : RU11207392
Date of Accident : 28.12.2021

No	Qty	Description	Amount \$
		List Items:-	
1	1	Front LH Fender	\$ <i>12</i> 170.00 <i>X</i>
2	1	Front LH Fender Inner Panel	\$ <i>12</i> 280.00 <i>X</i>
3	1	Front LH Fender Shield	\$ <i>12</i> 70.00 <i>X</i>
4	1	Front LH Fender Wheel Arch	\$ <i>12</i> 40.00 <i>X</i>
5	1	Front Bonnet	\$ <i>32</i> 380.00 <i>✓</i>
6	1	Front LH Bonnet Hinge	\$ <i>12</i> 30.00 <i>X</i>
7	1	Bonnet Insulator	\$ <i>12</i> 70.00 <i>X</i>
8	1	Bonnet Stand	\$ <i>12</i> 15.00 <i>X</i>
9	1	Bonnet Lock Bracket	\$ <i>20</i> 20.00 <i>?</i>
10	1	Front Radiator Top Cover	\$ <i>12</i> 50.00 <i>X</i>
11	1	Front Grille Base	\$ <i>180</i> 180.00 <i>?</i>
12	1	Front Grille Outer Garnish	\$ <i>140</i> 140.00 <i>✓</i>
13	1	Front Lower Bumper Grille	\$ <i>45</i> 45.00 <i>✓</i>
14	1	Front Grille Lower Moulding	\$ <i>40</i> 40.00 <i>✓</i>
15	1	Front Emblem	\$ <i>15</i> 15.00 <i>✓</i>
16	1	Front Bumper	\$ <i>300</i> 300.00 <i>✓</i>
17	2	Front Bumper Side Retainer	\$ <i>20</i> 20.00 <i>✓</i>
18	1	Front Bumper Under Cover	\$ <i>65</i> 65.00 <i>X</i>
19	1	Front Bumper Lower Lip	\$ <i>120</i> 120.00 <i>?</i>
20	1	Front RH Headlamp <i>LH</i>	\$ <i>780</i> 780.00 <i>✓</i>
21	1	Front RH Headlamp Lower Bracket	\$ <i>20</i> 20.00 <i>?</i>
22	1	Front RH Headlamp Top Bracket	\$ <i>10</i> 10.00 <i>?</i>
23	1	Front RH Bumper Lower Side Garnish	\$ <i>115</i> 115.00 <i>X</i>
24	1	Front RH Fog Lamp	\$ <i>15</i> 15.00 <i>X</i>
25	1	Front RH Fog Lamp Garnish	\$ <i>12</i> 12.00 <i>X</i>
26	1	Towing Cover	\$ <i>45</i> 45.00 <i>X</i>
27	1	Spare Tank / Washer Tank	\$ <i>295</i> 295.00 <i>X</i>
28	1	Support Panel	\$ <i>416</i> 416.00 <i>✓</i>
29	1	Aircon Condenser	\$ <i>172</i> 172.00 <i>?</i>
30	1	Aircon Condenser Fan Motor	\$ <i>60</i> 60.00 <i>?</i>
31	1	Aircon Fan Cowling	\$ <i>60</i> 60.00 <i>?</i>
Total - List Item			\$ 3,990.00
LESS 20%			\$ 798.00
Total			\$ 4,788.00

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05-01/06, Singapore Land Tower,
Singapore 048623
Attn: Accident Claims Department

Date : 28.12.2021
Vehicle No : SFF2500H
Veh Make/Model : Honda Vezel 1.5X CVT
YOM : 2016
Chassis No : RU11207392
Date of Accident : 28.12.2021

No	Qty	Description	Amount \$
List Items:-			
32	1	Aircon Fan Blade	\$ 40.00
33	1	Radiator	\$ 695.00
34	1	Radiator Fan Motor	\$ 150.00
35	1	Reinforcement Bar	\$ 180.00
36	1	Radiator Fan Cowling	\$ 65.00
37	1	Radiator Fan Blade	\$ 40.00
Total - List Item			\$ 1,170.00
LESS 20%			\$ 234.00
Total			\$ 1,404.00

Special Nett Items:-			
1	Set	Front LH Fender Shield Clips	\$ 35.00
2	Set	Front Bumper Clips	\$ 35.00
3	Set	Front LH Fender Wheel Arch Clips	\$ 35.00
4	Set	Front Radaitor Top Garnish Clips	\$ 38.00
5	Set	Front Bonnet Insulator Clips	\$ 38.00
6			
Total - SN Item			\$ 181.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

Compo Insurance Singapore Pte Ltd

10 Raffles Place

05-01/06, Singapore Land Tower,
Singapore 048623

Attn: Accident Claims Department

Date : 28.12.2021
Vehicle No : SFF2500H
Veh Make/Model : Honda Vezel 1.5X CVT
YOM : 2016
Chassis No : RU11207392
Date of Accident : 28.12.2021

No	Qty	Description	Amount \$
		Labour Charges:-	
1		Spray painting on all affected area	\$ 1,000.00
2		Labour remove/refit accident damages parts to straighten up, jack out, cut/weld and realign accident affected areas.	\$ 1,000.00
3		Check Wiring System & Light	\$ 100.00
4		Anti Rush Treatment	\$ 120.00
5		To Check & Adjust Wheel Adjustment	\$ 100.00
6		To Check & Adjust Front Main Chassis	\$ 380.00
7		To Remove/Refix Necessary Attachment Support Panel	\$ 280.00
8		Computer Disgnosis After Repair	\$ 350.00
9		To Remove/Refix/Replace Aircon Condensor (Top Up Aircon Gas Etc)	\$ 120.00
10		To Remove/Refix/Replace Radiator (piping/hose, top up radiator coolant & etc)	\$ 120.00
11		To Check & Adjust Front Main Chassis	\$ 250.00
12			
13			
		Total - L/C	\$ 3,820.00
		Sub-Total	\$ 10,193.00
		7% GST	\$ 713.51
		Total	\$ 10,906.51

600L
500
200
X
X
X
X
7
1000
7
X

ASSIGNMENT

SA1J21CS0001 / ACCORD AUTO SERVICES PTE LTD[568047]
 ENTRY DATE & TIME: 28/12/2021 17:02 (SGT)
 SUBMITTED BY: GOH JACQUELINE
 VERSION: 1 (28/12/2021 17:02 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 28/12/2021 17:02 (SGT)
 Date of Accident 28/12/2021 12:30 (SGT)
 Exact Location of Accident TPE, Singapore
 Additional Location Information Slip Road TPE (CTE/SLE) Toward Changi Village
 Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SFF2500H

INSURED/POLICYHOLDER

Is company? No
 Name Of Registered Owner Abdul Rahim Bin Mohamed
 NRIC No SXXXX942J
 Email Address fa_ra_sya@hotmail.com
 Mobile Phone No (Phone) +65-97620623
 Alternative Phone No +65-93665594

VEHICLE PARTICULARS

Manufacturer Honda
 Model Vezel
 Variant -
 Exact purpose for which vehicle was being used at time of accident Private use
 Are you claiming under your own insurance policy for repair to your vehicle? Yes
 Vehicle Category Private car
 Transmission Auto
 CC 1500

INSURANCE COMPANY

Name of Insurance Company Sompo Insurance Singapore Pte. Ltd.
 Type of Coverage Comprehensive
 Meet Policy No
 Policy Number D21MTPV01003564
 Cover Note Number -


DRIVER

Name of Driver Abdul Rahim Bin Mohamed
 NRIC No SXXXX942J

Accident report SA1J21CS0001

Sketch Plan

Slip Rd TPE (CTE / SLE)
board Chang Village



Describe Circumstances of the Accident

Location: Slip Rd. TPE (LTE/SLE) toward

Date of Accident : 28/12/21

Time of Accident : 12.05 PM

Vehicle A: ~~SFF~~ 2500H

Vehicle B: 8103216J

Vehicle C :

I stopped to check oncoming vehicle, traffic was cleared so I proceed to move out and infront vehicle is suddenly brake, as I couldn't brake in time I collided into his rear

Declaration

Declaration
We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

28 DEC 2021