

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

*Not Authored**Penny Bypain**5 days***ESTIMATE**

Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05-01/06, Singapore Land Tower,
Singapore 048623
Attn: Accident Claims Department

Date : 28.12.2021
Vehicle No : SFF2500H
Veh Make/Model : Honda Vezel 1.5X CVT
YOM : 2016
Chassis No : RU11207392
Date of Accident : 28.12.2021

No	Qty	Description	Amount \$
List Items:-			
1	1	Front LH Fender	\$ <i>12</i> 170.00
2	1	Front LH Fender Inner Panel	\$ <i>12</i> 280.00
3	1	Front LH Fender Shield	\$ <i>12</i> 70.00
4	1	Front LH Fender Wheel Arch	\$ <i>12</i> 40.00
5	1	Front Bonnet	\$ <i>32</i> 380.00
6	1	Front LH Bonnet Hinge	\$ <i>12</i> 30.00
7	1	Bonnet Insulator	\$ <i>12</i> 70.00
8	1	Bonnet Stand	\$ <i>12</i> 15.00
9	1	Bonnet Lock Bracket	\$ <i>20</i> 20.00
10	1	Front Radiator Top Cover	\$ <i>12</i> 50.00
11	1	Front Grille Base	\$ <i>180</i> 180.00
12	1	Front Grille Outer Garnish	\$ <i>140</i> 140.00
13	1	Front Lower Bumper Grille	\$ <i>45</i> 45.00
14	1	Front Grille Lower Moulding	\$ <i>40</i> 40.00
15	1	Front Emblem	\$ <i>15</i> 15.00
16	1	Front Bumper	\$ <i>300</i> 300.00
17	2	Front Bumper Side Retainer	\$ <i>20</i> 20.00
18	1	Front Bumper Under Cover	\$ <i>65</i> 65.00
19	1	Front Bumper Lower Lip	\$ <i>120</i> 120.00
20	1	Front RL Headlamp <i>CH</i>	\$ <i>780</i> 780.00
21	1	Front LH Headlamp Lower Bracket	\$ <i>20</i> 20.00
22	1	Front LH Headlamp Top Bracket	\$ <i>10</i> 10.00
23	1	Front RH Bumper Lower Side Garnish	\$ <i>115</i> 115.00
24	1	Front RH Fog Lamp	\$ <i>15</i> 15.00
25	1	Front RH Fog Lamp Garnish	\$ <i>12</i> 12.00
26	1	Towing Cover	\$ <i>45</i> 45.00
27	1	Spare Tank / Washer Tank	\$ <i>295</i> 295.00
28	1	Support Panel	\$ <i>416</i> 416.00
29	1	Aircon Condenser	\$ <i>172</i> 172.00
30	1	Aircon Condenser Fan Motor	\$ <i>60</i> 60.00
31	1	Aircon Fan Cowling	
Total - List Item			\$ 3,990.00
LESS 20%			\$ 798.00
Total			\$ 4,788.00

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05-01/06, Singapore Land Tower,
Singapore 048623
Attn: Accident Claims Department

Date : 28.12.2021
Vehicle No : SFF2500H
Veh Make/Model : Honda Vezel 1.5X CVT
YOM : 2016
Chassis No : RU11207392
Date of Accident : 28.12.2021

No	Qty	Description	Amount \$
List Items:-			
32	1	Aircon Fan Blade	\$ 40.00
33	1	Radiator	\$ 695.00
34	1	Radiator Fan Motor	\$ 150.00
35	1	Reinforcement Bar	\$ 180.00
36	1	Radiator Fan Cowling	\$ 65.00
37	1	Radiator Fan Blade	\$ 40.00
Total - List Item			\$ 1,170.00
LESS 20%			\$ 234.00
Total			\$ 1,404.00

Special Nett Items:-			
1	Set	Front LH Fender Shield Clips	\$ 35.00
2	Set	Front Bumper Clips	\$ 35.00
3	Set	Front LH Fender Wheel Arch Clips	\$ 35.00
4	Set	Front Radaitor Top Garnish Clips	\$ 38.00
5	Set	Front Bonnet Insulator Clips	\$ 38.00
6			
Total - SN Item			\$ 181.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

Compo Insurance Singapore Pte Ltd

10 Raffles Place

05-01/06, Singapore Land Tower,
Singapore 048623

Attn: Accident Claims Department

Date : 28.12.2021
Vehicle No : SFF2500H
Veh Make/Model : Honda Vezel 1.5X CVT
YOM : 2016
Chassis No : RU11207392
Date of Accident : 28.12.2021

No	Qty	Description	Amount \$
		Labour Charges:-	
1		Spray painting on all affected area	\$ 1,000.00
2		Labour remove/refit accident damages parts to straighten up, jack out, cut/weld and realign accident affected areas.	\$ 1,000.00
3		Check Wiring System & Light	\$ 100.00
4		Anti Rush Treatment	\$ 120.00
5		To Check & Adjust Wheel Adjustment	\$ 100.00
6		To Check & Adjust Front Main Chassis	\$ 380.00
7		To Remove/Refix Necessary Attachment Support Panel	\$ 280.00
8		Computer Disgnosis After Repair	\$ 350.00
9		To Remove/Refix/Replace Aircon Condensor (Top Up Aircon Gas Etc)	\$ 120.00
10		To Remove/Refix/Replace Radiator (piping/hose, top up radiator coolant & etc)	\$ 120.00
11		To Check & Adjust Front Main Chassis	\$ 250.00
12			
13			
		Total - L/C	\$ 3,820.00
		Sub-Total	\$ 10,193.00
		7% GST	\$ 713.51
		Total	\$ 10,906.51

600L
504
201
X
X
X
X
7
100L
7
X