

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Derrick Tan Ming Chye

Date: 03 Jan 2022

Preliminary Advice

Vehicle No	: SLX6698D	Accident Date	: 30/12/2021
Make	: TOYOTA VELLFIRE	Policy No.	: D20MFL0000326_01
Assignment Date	: 03/01/2022	Excess	: S\$0.00
Date of Inspection	: 3/1/2022	Est. Duration of Repair	: 4
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,272.61
Revised Amount	:S\$	2,257.89
Check Items (Estimated)	:S\$	120.00
Total	:S\$	2,377.89
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	200,000.00
COE / PARF Rebate	:S\$	92,578.00
Salvage Value	:S\$	
Margin for Repair	:S\$	107,422.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .