

PREMIUM AUTOMOBILES



55 UBI ROAD 1 SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUM-AUTO.COM.SG / CLAIMS@PREMIUM-AUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1071/2021/GW
DATE : 29-Dec-21
WIP :

Denise

\$7612.16.

06 days H.S.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 1

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR PUNG YONG HIN (FENG RONGXING)
ADDRESS : 57 WEST COAST WAY
#02-13
SINGAPORE 127018
TELEPHONE : HP +65 97931273
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700074799-04
VEHICLE NO : SLT 7852 P
MODEL CODE : A4 SEDAN 1.4 TFSI S
MODEL YEAR : 10/11/2017
ENGINE NO : CVN041444
CHASSIS NO : WAUZZZF41HA181818
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Dec-21
PLACE OF ACCIDENT : ALONG CLEMENTI AVE 2

PREMIUM AUTOMOBILES



55 UBI ROAD 1 SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLT 7852 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	+ ✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE	S/N \$ 700.00	+ ✓
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM VACUUM AND REGAS	S/N \$ 1,400.00	+ ✓
4	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGH. TO REPAIR BONNET AND BOTH FENDERS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,500.00	SSS 750
5	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDER AND BONNET.	\$ 3,500.00	SSS 1100
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓ SSS
TOTAL LABOUR CHARGES		: \$ 10,652.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408659

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 7852 P

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Del</i>	1	\$ 2,111.00	✓	1688.98
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	TBC	+	
3	FRONT BUMPER SECURING STRIP <i>new</i>	2	\$ 71.00	+	
4	FRONT BUMPER GRILLE - CENTER <i>cracked</i>	1	\$ 196.00	✓	156.4
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>cr</i>	1	\$ 210.00	+	
6	FRONT BUMPER AIR GUIDE - LH / RH <i>new</i>	2	\$ 126.00	+	
7	RADIATOR GRILLE <i>cracked</i>	1	\$ 1,152.00	✓	921.6
8	FRONT AIR GUIDE GRILLE - LH / RH <i>new</i>	2	\$ 270.00	+	
9	FRONT FOAM FILLER PIECE <i>cracked</i>	1	\$ 124.00	✓	99.2
10	FRONT BUMPER REINFORCEMENT BEAM <i>dented</i>	1	\$ 845.00	✓	675.6
11	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	1	\$ 36.00	+	
12	FRONT BUMPER GUIDE SECTION - RH <i>new</i>	1	\$ 38.00	+	
13	FRONT REINFORCEMENT BEAM BRACKET - LH / RH <i>new</i>	2	\$ 456.00	+	364
14	FRONT BUMPER COVER <i>cracked</i>	1	\$ 127.00	✓	101.6
15	SIGN CAUTION STICKER <i>new</i>	1	\$ 14.00	✓	10.88
16	AIR CONDITIONER STICKER <i>new</i>	1	\$ 8.00	✓	5.68
17	FRONT LOCK CARRIER BRACKET <i>cracked</i>	1	\$ 137.00	✓	109.6
18	FRONT LOCK CARRIER SUPPORT - LH / RH <i>cracked</i>	2	\$ 58.00	✓	44.96
19	FRONT HORN - LH / RH <i>new</i>	2	\$ 252.00	+	
20	FRONT HORN BRACKET - LH / RH <i>new</i>	2	\$ 58.00	+	
SUB TOTAL SPARE PARTS			\$ 6,289.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408099
TEL: 6366 2123 FAX: 6341 1183
EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 7852 P

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	LED HEADLIGHT - LH / RH <i>new</i>	2	\$ 15,386.00	+	
22	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM - LH	1	\$ 210.00	+	
23	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM - RH	1	\$ 210.00	+	
24	RORUGATED PIPE FOR HEADLIGHT WASHER SYSTEM	1	\$ 93.00	+	
25	FRONT LOCK CARRIER <i>new</i>	1	\$ 1,016.00	+	
26	RADIATOR SUPPORT BRACKET - LH / RH <i>could</i>	2	\$ 76.00	✓	60.64
27	A/C CONDENSER	1	\$ 622.00	+	
28	A/C CONDEMSEK BRACKET	1	\$ 19.00	+	✓ 14.56
29	RADIATOR	1	\$ 655.00	+	
30	ADDITIONAL RADIATOR	1	\$ 511.00	+	
31	RADIATOR COOLANT <i>new</i>	6	\$ 266.00	+	
32	RADIATOR AIR GUIDE LH / RH	2	\$ 56.00	✓	44.64
33	RADIATOR INNER AIR GUIDE LH / RH	2	\$ 24.00	✓	18.88
34	RADIATOR LOWER AIR GUIDE	1	\$ 22.00	+	
35	RADIATOR CENTRE AIR GUIDE	1	\$ 16.00	+	
36	FRONT NO PLATE <i>new</i>	S/N	\$ 60.00	✓	60
37	SUNDRIES		\$ 350.00	✓	2.56
TOTAL SPARE PARTS			\$ 25,881.00		
TOTAL LABOUR CHARGES			\$ 10,652.00		
GRAND TOTAL			\$ 36,533.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adam Ly
31/12/21

Not authorised, 03 Days
06 Days H.S.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT