



ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S8000025 / TPCL	Service Retail Cash Sales Body & Paint Service Retail Cash Sales Body & Paint
	Document No. 0	
	Document Date 14/01/2022	

Year	Model	Variants	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	SWIFT	2LM1CXF35	25/03/2020	SNC7425E	0	12127	72/DS/SNC7425E

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
J5AAZC13S00303724	K10C1263759	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	S	S-BMS TP INS: TP VEH:MID46346 DATE OF ACC:29.12.2021		50.00		50.00
2	S	S-BMS REPLACE AND REFOCUS HEADLAMP		99.62		99.62
3	S	S-BMS TO RESET ECU AND REPROGRAMME		146.50		146.50
4	S	S-BMS R/I FRONT BUMPER SPOILER TO FAC REPAIR.		146.50		146.50
5	S	S-BMS TO CONDUCT ADJUSTMENT ON FRONT RADAR SEN SOR		146.50		146.50
6	S	S-BMS REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS		586.00		586.00
7	S	S-BMS RESPRAY ACC AFFECTED AREAS		484.00		484.00
8	1	S35320-52RF0-000 UNIT,HEADLAMP,L	1.00	1727.40		1727.40
9	2	S71732-53R00-000 HOLDER,FR BUMPER SIDE,L	1.00	7.35		7.35
10	3	S71734-52R00-000 HOLDER,FR BUMPER FR,L	1.00	8.40		8.40

For & on behalf of	Customer's Signature	Charge Summary	Total
Champion Motors (1975) Pte Ltd			3,402.27
	Please acknowledge receipt of vehicle	Parts 1,743.15	GST 7.00% 238.16
		Labour 0.00	Less 0.00
		Sublet 1,659.12	
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 3,640.43