

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: 3051/01/22

Your Ref:

Date: 3rd Jan 2022

The Claim's Manager  
Motor Claims Dept.  
INDIA INTERNATIONAL INSURANCE PTE. LTD.  
64, Cecil Street, #05-00, IOB Bldg.  
Singapore 049711

Name Of Insured : Mr Ang Eek Koon  
Date Of Accident : 01/01/22 (14:30hrs)  
Policy Number: D19MPC0001672\_02

*Not Authorized  
hell?  
Express \$?  
1/5 #3050 |  
Hdngs.  
The ph. Address*

Estimate cost of repair to BMW 216i GT LED (A) 1.5 SUV - SJK 8941 E

1 pc front bonnet	120	\$ 1,086.00	
12 pcs front bonnet insulator clips	11	108.00	X
1 pc front bumper	de/cut	985.00	
1 set front bumper clips	60	180.00	
1 pc front bumper logo emblem		SUL 78.00	X
1 pc front bumper n/s grille (with chrome)		C12 128.00	
1 pc front bumper centre lower air scoop grille		7W1 135.00	
1 set front bumper rivets	80	180.00	
1 pc front bumper sponge damper		SUL 65.00	X
1 pc front bumper reinforcement		11 395.00	X
1 pc front number plate garnish		DE 85.00	
1 pc front number plate with BMW frame		C12 100.00	40 S/N
1 set front bumper o/s & n/s outer sensor		SU 656.00	X
1 set front bumper o/s & n/s inner sensor		SU 656.00	X
1 pc n/s head lamp assy		11 976.00	X
1 pc for o/s grille	C12	\$128.00	
		\$ 5,813.00	
		Less 5%	\$ 290.65
			\$ 5,522.35

To wiring check up & adjust headlight alignment. 80.00 30

To diagnose & re-set front bumper sensor. 150.00 50

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out necessary parts, to weld, renew & align above parts. 900.00 600

To putty & respray painting on all affected accident parts. 1,300.00 600

\$ 7,952.35  
=====

Dollars : Seven Thousand Nine Hundred and Cents Thirty Five Only.

HUP MOTOR TRADING & SERVICE

*[Signature]*

I, KK Auto Consultant, hereby certify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

P-2647  
52  
P-25148  
S/N 40  
1280  
L-  
387465