



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22000019/Utf3n2	
			Date: 09/02/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKL 633E	Veh. Inspected	SNC 2341X
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2103153/AGC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	03/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA FIT (A)	c.c	1317
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	GR11023462	Colour	BLACK
	Odometer	3316 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	YOKOHAMA	8 mm
	L/H Front Tyre	185/60 R15	YOKOHAMA	8 mm
	R/H Rear Tyre	185/60 R15	YOKOHAMA	8 mm
	L/H Rear Tyre	185/60 R15	YOKOHAMA	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	22/10/2021	Inspection Date	04/01/2022
	Survey held at	JACK CARS ENTERPRISE PTE LTD BLK 3007 UBI ROAD 1 #01-450 SINGAPORE 408700		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	