



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV16435/Seah Min Fann
	Reg No/Reg Date	SKZ6596R*KC17/ 29/01/201
	Date In/Mileage	/ 0
	Chassis No	KNAFZ411MF5537893
	Engine No	G4FGFH600855
	Make/Model	KIA/FORTE K3 1.6 A SX ADQ
	Colour/Trim	SWP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
LAX00000	Credit	03/01/2022/ 13:59		282 / Kevin Leong	44933	
Description of Goods / Services						
			Qty	Unit Price	Disc%	Amount
E PNT88000		REPLACE REAR LH FENDER, REAR LH DOOR & AFFECTED AREA REPAIR ON REAR BUMPER				1600.00
E PNT98000		PAINT WORK ON REAR LH FENDER, REAR LH DOOR & REAR BUMPER				1050.00
E PNT88000		REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR				240.00
M SUNDRY		TO APPLY WINDSCREEN SEALANT				80.00
E PNT88000		REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR				120.00
E PNT88000		REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR				120.00
E PNT88000		TO TRANSFER REAR LH DOOR ATTACHMENTS TO NEW PANEL				120.00
A 13900099		REMOVE & INSTALL FUEL TANK FOR FACILITATE REPAIR				400.00
M SUNDRY		TO APPLY SEALANT ON AFFECTED AREA				120.00
M SUNDRY		PERFORM RUST PREVENTION				120.00
A 54900099		CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901		TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
E PNT88000		REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR				80.00
M SUNDRY		SUNDRIES				40.00
M		PANEL ASSY-QUARTER OUTER,LH	1.00	1213.00	20.00	970.40
M		PANEL ASSY-REAR DOOR,LH	1.00	1361.00	20.00	1088.80
M		W/STRIP ASSY-RR DR BELT O/S RH	1.00	89.00	20.00	71.20
M		W/STRIP ASSY-RR DR SIDE LH	1.00	114.00	20.00	91.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV16435/Seah Min Fann
	Reg No/Reg Date	SKZ6596R*KC17/ 29/01/201
	Date In/Mileage	/ 0
	Chassis No	KNAFZ411MF5537893
	Engine No	G4FGFH600855
	Make/Model	KIA/FORTE K3 1.6 A SX ADQ
	Colour/Trim	SWP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	03/01/2022/ 13:59		282 / Kevin Leong	44933

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M GLASS ASSY-REAR WINDOW	1.00	534.00	20.00	427.20
M MOULDING-REAR WINDOW GLASS	1.00	27.00	20.00	21.60
M STOPPER-RR WINDOW GLASS	2.00	4.00	20.00	6.40
M PAD-WINDSHIELD GLASS	10.00	2.00	20.00	16.00
M BLACK TAPE-RR DR FRAME UPR,LH	1.00	11.00	20.00	8.80
M BLACK TAPE-RR DR FRAME RR,LH	1.00	8.00	20.00	6.40

Estimate

Confirm & accepted by

	Nett	6,948.00
7% GST on	6948.00	486.36
Total Payable		7,434.36

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.