



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
 Tel: +65 67412845 Fax No: +65 67412170
 Email: zero_gravity@singnet.com.sg
 Reg.No.: 52888887X

QUOTATION

No : QT-000270

AIG ASIA PACIFIC INSURANCE PTE. LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

Attention: Motor Claim Department

TEL : 64193000

FAX :

Your Ref. : SLR5696Y
 Vehicle No. : SLK460E
 Make & Model : TOYOTA HARRIER
 Chasis No. : ZSU600056717
 Engine No. : 3ZRB633761
 Accident Date : 28/12/2021
 Policy No. : 5117217165-01
 Date : 03/01/2022
 Page : 1 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S.
1	SHOCK ABSORBER (L/H/F) <i>new</i>	1.0	PCS 528.72	<i>x</i> 528.72
2	LOWER ARM (L/H/F) <i>Bent</i>	1.0	PCS 439.54	<i>✓</i> 439.54
3	STEERING KNUCKLE (FRONT) <i>new</i>	1.0	PCS 536.14	<i>x</i> 536.14
4	WHEEL BEARING (L/H/F) <i>new</i>	1.0	PCS 511.31	<i>✓</i> 511.31
5	STEERING LINKAGE (L/H) <i>new</i>	1.0	PCS 130.35	<i>x</i> 130.35
6	FENDER (L/H) <i>Repair</i>	1.0	PCS 789.52	<i>x</i> 789.52
7	FENDER INNER GARNISH (L/H/F) <i>new</i>	1.0	PCS 398.09	<i>x</i> 398.09
8	FENDER INNER GARNISH CLIP	8.0	PCS 5.00	<i>x</i> 40.00
9	FRONT BUMPER <i>behind</i>	1.0	PCS 558.54	<i>✓</i> 558.54
10	BUMPER CLIP <i>new</i>	10.0	PCS 5.00	<i>30</i> 50.00
11	BUMPER SIDE RETAINER (L/H/F) <i>new</i>	1.0	PCS 87.75	<i>✓</i> 87.75
12	FRONT BUMPER SPONGE (L/H) <i>new</i>	1.0	PCS 64.52	<i>✓</i> 64.52
13	HEADLIGHT (L/H) <i>new</i>	1.0	PCS 3,584.75	<i>3303</i> 3,584
14	HEADLIGHT LOWER BRACKET (L/H) <i>new</i>	1.0	PCS 81.64	<i>x</i> 81.64
15	FOG LIGHT (L/H) <i>new</i>	1.0	PCS 228.08	<i>✓</i> 228.08
16	FOG LIGHT GARNISH (L/H) <i>new</i>	1.0	PCS 126.04	<i>✓</i> 126.04
17	Discount 25 %			-2,038.75
18	SubTotal (L)			6,116.24
19	SPORT RIM (L/H/F) <i>new</i>	1.0	PCS 350.00	<i>✓</i> 350.00
20	TYRE (L/H/F) <i>new</i>	1.0	PCS 150.00	<i>✓</i> 150.00
21	SubTotal (S)			500.00
22	PANEL BEAT & REPAIR FRONT DAMAGE	1.0	X	<i>500</i> 800.00
23	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1.0	X	<i>600</i> 900.00
24	TO CHECK UNDERCARRIAGE AND REPLACE DAMAGED PARTS	1.0	X	<i>180</i> 250.00
25	TO COMPUTERISE ADJUST WHEEL ALIGNMENT	1.0	X	<i>80</i> 100.00
26	TO PROVIDE UNDER TURF COAT	1.0	X	<i>50</i> 120.00
27	TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS	1.0	X	<i>30</i> 50.00

xiao tong

5348.78

4011.58

500

1440



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
Tel: +65 67412845 Fax No: +65 67412170
Email: zero_gravity@singnet.com.sg
Reg.No.: 52888887X

QUOTATION

No : QT-000270

AIG ASIA PACIFIC INSURANCE PTE. LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attention: Motor Claim Department

TEL : 64193000

FAX :

Your Ref. : SLR5696Y
Vehicle No. : SLK460E
Make & Model : TOYOTA HARRIER
Chasis No. : ZSU600056717
Engine No. : 3ZRB633761
Accident Date : 28/12/2021
Policy No. : 5117217165-01
Date : 03/01/2022
Page : 2 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
28	SubTotal (LABOUR)			2,220.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 5951.58

1/5: 4750

050m/s

4750

SINGAPORE DOLLAR EIGHT THOUSAND EIGHT HUNDRED THIRTY SIX AND CENTS TWENTY
FOUR ONLY

E. & O.E

Total	S\$	8,836.24
Discount	S\$	0.00
Net Total	S\$	8,836.24

Terms: C.O.D.

Customer's Signature/Co. Stamp

ZERO GRAVITY

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.