



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22000033/Ktf3q2 Date: 01/04/2022 Code: SMO	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SMM 9604B
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2200001/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	03/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA HRV (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	JHMRU1810JX201925	Colour	METALLIC DARK BLUE
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	YOKOHAMA	9 mm
	L/H Front Tyre	215/60 R16	YOKOHAMA	9 mm
	R/H Rear Tyre	215/60 R16	YOKOHAMA	9 mm
	L/H Rear Tyre	215/60 R16	YOKOHAMA	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/12/2021	Inspection Date	04/01/2022
	Survey held at	NO 8 MANDAI ESTATE		
	Repairer	KAH MOTOR.CO.SDN.BHD		
5a. Remarks				
	A)THE MARKET VALUE IS S\$84,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days