

ASS. REC. BY:

REF: *TH***KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: SOMPO INSURANCE SINGAPORE PTE LTD	Document No.	: SQT22000001	Page	1
	50 RAFFLES PLACE #03-03	Date	: 3. Jan 2022		
	SINGAPORE LAND TOWER	Customer No.	: WH023		
	SINGAPORE 048623	Svc Advisor	: ANIKKA LAI SWEE KAM		
Registration No	: SMM9604B	Engine No	: L15B5671927		
Chassis No	: JHMRU1810JX201925	Date Time	: 3. Jan 2022 8:41:19 AM		
Model	: HRV DX-SIN CVT YM 2018	Surveyor Name	:		
Owner's Name	: JAY YEO SHENG QUAN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 30/12/2021				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST	
	OWN DAMAGE CLAIMS-J/NO:							
	POLICY/CLAIMS NO:							
	OWNER: JAY YEO SHENG QUAN							
	ACC DATE: 30/12/2021							
	SURVEYED BY:							
	DATE:							
	AUTHORIZED ON :							
	REF NO :							
04711-T7A-J00ZZ	FACE,FR.BUMPER	<i>Bt/cm</i> 1	507.10	25	380.32	26.62	406.94	✓
71193-T7A-J00	SPACER,R.FR.BUMPER SIDE	<i>Dit</i> 1	11.70	25	8.77	0.61	9.38	✓
71198-T7A-J00	SPACER,L.FR.BUMPER SIDE	<i>Dit</i> 1	11.70	25	8.77	0.61	9.38	✓
91505-TM8-003	CLIP,BUMPER	<i>me</i> 1	2.30	25	1.72	0.12	1.84	✓
71102-T7A-J20	FACE,FR.BUMPER LOWER	<i>Dit</i> 1	345.90	25	259.42	18.16	277.58	✓
71103-T7A-J00	GRILLE,FR.BUMPER LOWER	<i>Dit</i> 1	86.40	25	64.80	4.54	69.34	✓
71104-T7A-J00ZH	COVER,FR.TOWING HOOK	<i>su</i> 1	17.50	25	13.12	0.92	14.04	✗
71105-T7A-J10	GARNISH,R.FR.FOG LIGHT	<i>su</i> 1	25.90	25	19.42	1.36	20.78	✗
71106-T7A-J10	GARNISH,L.FR.FOG LIGHT	<i>su</i> 1	25.90	25	19.42	1.36	20.78	✗
71107-T7A-J00	BRACKET,R.FOG LIGHT	<i>su</i> 1	21.60	25	16.20	1.13	17.33	✗
71108-T7A-J00	BRACKET,L.FOG LIGHT	<i>su</i> 1	21.60	25	16.20	1.13	17.33	✗
71110-T7A-J00	SPOILER,FR.BUMPER AIR	1	58.80	25	44.10	3.09	47.19	?
71111-T7A-J00	GUIDE,R.FR.BUMPER AIR	1	30.40	25	22.80	1.60	24.40	?
71116-T7A-J00	GUIDE,L.FR.BUMPER AIR	1	30.40	25	22.80	1.60	24.40	?
71130-T7A-J00ZZ	BEAM COMP,FR.BUMPER	<i>Bt</i> 1	259.40	25	194.55	13.62	208.17	✓
71140-T7A-J00	BEAM,R.FR.BUMPER UPPER	<i>GPA</i> 1	33.70	25	25.27	1.77	27.04	?
71190-T7A-J00	BEAM,L.FR.BUMPER UPPER	<i>Dit</i> CM 1	33.70	25	25.27	1.77	27.04	✓
71161-T7A-000	GARNISHR.FR.BUMPER BEAM	<i>CM</i> 1	8.20	25	6.15	0.43	6.58	✓
71166-T7A-000	GARNISHL.FR.BUMPER BEAM	<i>CM</i> 1	8.20	25	6.15	0.43	6.58	✓
71121-T7A-G01	BASE,FR.GRILLE	<i>CM</i> 1	233.10	25	174.82	12.24	187.06	✓

Printed on 3/1/2022 2:06:46 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HONDA

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE #03-03
SINGAPORE LAND TOWER
SINGAPORE 048623
Registration No : SMM9604B
Chassis No : JHMRU1810JX201925
Model : HRV DX-SIN CVT YM 2018
Owner's Name : JAY YEO SHENG QUAN
Ins Policy No. :
Date of Accident : 30/12/2021

Document No. : SQT22000001
Date : 3. Jan 2022
Customer No. : WH023
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : L15B5671927
Date | Time : 3. Jan 2022 8:41:19 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71122-T7A-J01	MOLDING,FR.GRILLE UPPER	CM 1	227.00	25	170.25	11.92	182.17 ✓
71125-T7A-J01	BRACKET,FR.GRILLE	CM 1	129.70	25	97.27	6.81	104.08 2
71150-T7A-J00	BEAM,FR.GRILLE CENTER UPPER	CM 1	42.10	25	31.57	2.21	33.78 ✓
71151-T7A-J00	BEAM,R.FR.GRILLE SIDE UPPER	CM 1	18.70	25	14.02	0.98	15.00 ✓
71152-T7A-J00	BEAM,L.FR.GRILLE SIDE UPPER	CM 1	18.70	25	14.02	0.98	15.00 ✓
75700-T5A-000	EMBLEM H	M 1	17.20	25	12.90	0.90	13.80 ✓
90301-ST0-003	NUT,PUSH 3MM	M 1	2.10	25	1.57	0.11	1.68 ✓
19043-PNB-A00	LABELCOOLANT INFORMATION	M 1	5.40	25	4.05	0.28	4.33 ✓
80050-TG7-000	LABEL AIR CON	M 1	0.90	25	0.67	0.05	0.72 ✓
60100-T7A-000ZZ	HOOD COMP ENGINE	P 1	854.10	25	640.57	44.84	685.41 ✓
60120-T7A-G00ZZ	HINGE COMP,R.HOOD	D 1	48.40	25	36.30	2.54	38.84 2
60170-T7A-G00ZZ	HINGE COMP,L.HOOD	D 1	48.40	25	36.30	2.54	38.84 2
74120-T7A-003	LOCK ASSYHOOD	1	60.80	25	45.60	3.19	48.79 7
74141-T7A-000	INSULATORHOOD	P 1	117.00	25	87.75	6.14	93.89 X
60210-T7A-J00ZZ	PANEL COMP,R.FR.FENDER	R 1	421.10	25	315.82	22.11	337.93 X
60260-T7A-J00ZZ	PANEL COMPL.FR.FENDER	R 1	421.10	25	315.82	22.11	337.93 X
74157-T7B-003	PROTECTOR,L.FR.WHEEL ARCH	1	163.80	25	122.85	8.60	131.45 7
60400-T7A-901ZZ	BULKHEAD COMP,FR.	R 1	463.30	25	347.47	24.32	371.79 X
19010-50T-902	RADIATOR COMP	S 1	1291.70	25	968.77	67.81	1036.58 X
80110-T7A-003	CONDENSER COMP	P 1	568.10	25	426.07	29.82	455.89 ✓
33100-T7A-E51	HEADLIGHT ASSY,R.	1	1395.20	25	1046.40	73.25	1119.65 7
33150-T7A-E51	HEADLIGHT ASSY,L.	M 1	1395.20	25	1046.40	73.25	1119.65 ✓
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
Sum Item					7157.51	501.02	7,658.53
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00 7
3ML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00	1501	180.00	12.60	192.60
IMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	220.00	AN	220.00	15.40	235.40 X
MA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	280.00		280.00 ✓	19.60	299.60

Printed on 3/1/2022 2:06:46 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

A amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HONDA

KAH MOTOR CO. SDN. BHD.

(Member of the Oriental Holdings Berhad)

Service and Body Repair

+65 6841 3838

Website: www.honda.com.sg

or 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE #03-03
SINGAPORE LAND TOWER
SINGAPORE 048623
Registration No : SMM9604B
Chassis No : JHMRU1810JX201925
Model : HRV DX-SIN CVT YM 2018
Owner's Name : JAY YEO SHENG QUAN
Ins Policy No. :
Date of Accident : 30/12/2021

Document No. : SQT22000001 Page 3
Date : 3. Jan 2022
Customer No. : WH023
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : L15B5671927
Date | Time : 3. Jan 2022 8:41:19 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
BKBH01R	REMOVE & RENEW BULKHEAD AND RENEW DAMAGED PARTS	1	3000.00	19.50%	3000.00	210.00	3210.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	3000.00	20.80%	3000.00	210.00	3210.00
Sum Labor					6780.00	474.60	7,254.60

Survey By Kenneth
Date & Time 4/1/22
Excess _____
Status _____
Signature PC

Total Amount 13,937.51 975.62 14,913.13
Total (Inclusive of GST) **14,913.13**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 3/1/2022 2:06:46 PM

This is a computer generated invoice. No signature is required.

Prices are subjected to change without notice.

Our estimated cost of repair do not include any unforeseen damages.

Amount is calculated from individual line(s).

A surcharge of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

If the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.