

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATEDATE: 3-Jan-22INSURANCE: AIG ASIA CP/PDMODEL: Hyundai IoniqMVA: LIM T SVEHICLE NO.: SHC 801U - CityCab

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		Ry \$459.40
	Rear Bumper Centre Moulding Assy	1		Ry \$451.25
	Rear Bumper Clips	10	\$2.20	neu \$22.00
	SUB TOTAL		22	\$932.65
	LESS 20%			\$186.53
	DISCOUNTED TOTAL		17.60	\$746.12
	Reverse Sensors	1		W X \$180.00
	Rear No.Plates With Trim Cover	1		CU \$55.00
	S/NETT TOTAL		55	\$235.00
	SPARE PARTS TOTAL			\$981.12
	<u>Labour Charge</u>			
	Panel Beating		350	\$400.00
	Spray Painting Charge		250	\$300.00
	Remove/Refix Reverse Sensor		30	\$120.00
	TOTAL LABOUR		630	\$820.00
	ESTIMATE TOTAL		1702.60 + 2 days	\$1,801.12

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 17495741
 - WP 3/1/22 @ 5pm
 • 2 days
 1/1 Reusing new parts
 Tanpin Consultant

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: