



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22000037/Atf3n2	
			Date: 11/02/2022	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SJF 4024E	Veh. Inspected	SLT 5322R
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2200010/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	03/01/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	BMW 216I GT	c.c	1499
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WBA2D920005E91316	Colour	BLACK
	Odometer	32791 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/50 R17	YOKOHAMA	6 mm
	L/H Front Tyre	225/50 R17	YOKOHAMA	6 mm
	R/H Rear Tyre	225/50 R17	YOKOHAMA	6 mm
	L/H Rear Tyre	225/50 R17	YOKOHAMA	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	01/01/2022	Inspection Date	04/01/2022
	Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	