

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 01/01/2022

Estimated repair cost for vehicle no: SLT5322R BMW 216I GT LED NAV

CHASSIS: WBA2D920005E91316 (2017)

SUPPLEMENTARY

S/N	Qty	Items	U/price	Amount
1	2	REAR BUMPER SIDE BRACKET <i>angled</i>	\$254.00	\$508.00 160.
2	2	REAR EXHUAUST MUFFLER ALUMIMIUN SHIELD <i>angled</i>	\$459.00	\$459.00 177.
TOTAL :				\$967.00
LESS 5 %				\$48.35
SUB-TOTAL :				\$918.65

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR EXHUAUST CHROME PIPE <i>new</i>	\$180.00	\$180.00 +

TOTAL: \$180.00

TOTAL PARTS : \$1,098.65

237
303.30

Adrian
05/01/22.