



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22000038/Evy3e2	
			Date: 02/11/2022	
			Code: FCI2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SKX 5940Y
	Policy No.	D-20197719MVPC	Coverage (\$)	0.00
	Claim No.	D22000055MVPC	Excess (\$)	500.00
	Assign From	AINI BINTE	Assign Date	03/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA AXIO	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	NRE1610009069	Colour	SILVER
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/50 R16	BRIDGESTONE	4 mm
	L/H Front Tyre	205/50 R16	BRIDGESTONE	4 mm
	R/H Rear Tyre	205/50 R16	BRIDGESTONE	4 mm
	L/H Rear Tyre	205/50 R16	BRIDGESTONE	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	31/12/2021	Inspection Date	27/09/2022
	Survey held at	GOLDBELL ENGINEERING PTE LTD 10 TUAS AVE 18 SINGAPORE 638894		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE MARKET VALUE IS S\$55,000.00(EST. AVERAGE) C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	