

⏪	<	1 of 2 ?	>	⏩	↺	↻	100% ▼	🖨	📄	Find Next
---	---	----------	---	---	---	---	--------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref: CS/FCI22000038/f3		
36 ROBINSON ROAD		Date: 03/01/2022		
#16-01 CITY HOUSES SINGAPORE 068877		Code: FCI2		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		SKX 5940Y	
Policy No.	Coverage (\$)		0.00	
Claim No.	D22000055MVPC	Excess (\$)		0.00
Assign From	AINI BINTE	Assign Date		03/01/2022
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	31/12/2021	Inspection Date	03/01/2022	
Survey held at	GOLDBELL ENGINEERING PTE LTD 10 TUAS AVE 18 SINGAPORE 638894			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				