



GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co Reg No 199003953G

Page 1 / 3

ESTIMATE

Date	: 26/09/2022	Reg No	: SKX5940Y
To	: MS FIRST CAPITAL INSURANCE LIMITED	Model	: TOYOTA AXIO 1.5G A
Attn.	:	Chassis No	: NRE1610009069
Office / Mobile	:	Engine No	:
Email Address	:	Quotation No.	: 164983
		Ref. No.	: GBE/SVC/SALES-HQ/39-3112
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 31/12/2021
Attn.	: LIEWSIMING	Policy No.	: D-20197719MVPC
Office / Mobile	:	Claim Type	: OD CLAIM - MSFC
Email / Fax No.	: LiewSiMing@goldbell.com.sg	Workshop	: 8 TUAS AVE 18


S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		FRONT BONNET / <i>DD</i>	1	780.50	0	780.50	780.50
2		FRONT RIGHT FENDER / <i>DD</i>	1	480.30	0	480.30	480.30
3		FRONT RIGHT HEADLAMP / <i>BR</i>	1	1,653.60	0	1,653.60	1,653.60
4		FRONT BUMPER / <i>BR</i>	1	380.50	0	380.50	380.50
5		FRONT BUMPER LH RETAINER / <i>BR</i>	1	55.00	0	55.00	55.00
6		FRONT BUMPER RH RETAINER / <i>BR</i>	1	55.00	0	55.00	55.00
7		FRONT BUMPER ABSORBER / <i>BR</i>	1	280.00	0	280.00	280.00
8		FRONT BUMPER REINFORCEMENT / <i>?</i>	1	494.00	0	494.00	494.00
9		FRONT LOWER GRILLE / <i>MIS</i>	1	230.00	0	230.00	230.00
10		FRONT LEFT FOG LAMP COVER / <i>cut</i>	1	105.00	0	105.00	105.00
11		FRONT RIGHT FOG LAMP COVER / <i>cut</i>	1	105.00	0	105.00	105.00
12		FRONT LEFT DOOR / <i>DD</i>	1	1,080.30	0	1,080.30	1,080.30
13		FRONT LEFT DOOR UPPER HINGE / <i>X</i>	1	105.40	0	105.40	105.40
14		FRONT LEFT DOOR LOWER HINGE / <i>X</i>	1	105.40	0	105.40	105.40
15		LH SIDE SILL / <i>X</i>	1	192.00	0	192.00	192.00
16		FRONT LEFT RIM / <i>cut</i>	1	2,321.60	0	2,321.60	2,321.60
17		FRONT LEFT TYRE / <i>CR1 (80%)</i>	1	250.00	0	250.00	250.00
18		FRONT LEFT INNER SHIELD / <i>TH</i>	1	105.40	0	105.40	105.40
19		FRONT RIGHT INNER SHIELD / <i>MD</i>	1	105.40	0	105.40	105.40
20		INNER SHIELD (CLIPS) / <i>MR</i>	20	5.50	0	5.50	110.00

PARTS TOTAL : 8,994.40

SPECIAL NETT ITEMS

1	FRONT NUMBER PLATE	1	35.00
---	--------------------	---	-------

PARTS TOTAL: 35.00



AIRMAN.





GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3876
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co Reg No: 198003953G

Page 2 / 3

ESTIMATE

Date :	26/09/2022	Reg No :	SKX5940Y
To :	MS FIRST CAPITAL INSURANCE LIMITED	Model :	TOYOTA AXIO 1.5G A
Attn. :		Chassis No :	NRE1610009069
Office / Mobile :		Engine No :	
Email Address :		Quotation No. :	164983
		Ref. No. :	GBE/SVC/SALES-HQ/39-3112
From :	GOLDBELL ENGINEERING PTE LTD	D.O.A. :	31/12/2021
Attn. :	LIEWSIMING	Policy No. :	D-20197719MVPC
Office / Mobile :		Claim Type :	OD CLAIM - MSFC
Email / Fax No. :	LiewSiMing@goldbell.com.sg	Workshop :	8 TUAS AVE 18

LABOUR CHARGES

1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC	1000 1200	2400.00
2	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK	35	180.00
3	TO TRANSFER DOOR COMPARTMENT / WINDOW GLASS / REGULATOR / LOCK / MECHANISM, ETC	50	350.00
4	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	1100	1750.00

LABOUR TOTAL :	4,680.00
SUB-TOTAL :	13,709.40
GST @ 7% for \$ 13,709.40	959.66
GRAND TOTAL (S\$) :	14,669.06

Steve (LKK)
27/9/22, 4:37

W L R
L/S
M M ay
7 4/5

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer



AIRMAN.

