

AIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jan 2022)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	ComfortDelGro Engineering Pte Ltd/SHA2222M/03/01/2022 13:55	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	de *459.40 FL
2	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	de *451.25 FL
3	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	cu *394.80 FL
4	2		*REAR BUMPER REINFORCEMENT STAY LH/RH	20.00	0.00	LAX *276.20 FL
5	1		*REAR BUMPER LOWER CENTRE COVER	20.00	0.00	Rm *225.00 FL
6	10		*REAR BUMPER CLIPS	20.00	0.00	in *22.00 FL
7	1		*BOOTLID COVER	20.00	0.00	H *2,480.40 FL
8	1		*BOOTLID EMBLEM H	20.00	0.00	rel *38.00 FL
9	1		*BOOTLID EMBLEM IONIQ	20.00	0.00	rel *31.80 FL
10	1		*BOOTLID EMBLEM HYBRID	20.00	0.00	rel *24.30 FL
11	1		*REAR BUMPER NUMBER PLATE LAMP	20.00	0.00	R *85.00 FL
12	1		*REAR BUMPER SMART KEY SENSOR	20.00	0.00	R *45.50 FL
13	1		*REAR BUMPER FOG LAMP	20.00	0.00	R *201.10 FL
14	2		*REAR BUMPER BRACKET LH /RH	20.00	0.00	R *111.60 FL
15	2		*REAR BUMPER REFLECTOR LH /RH	20.00	0.00	X *82.90 FL
16	1		*REAR END PANEL	20.00	0.00	Rp *532.00 FL
17	1		*REAR NUMBER PLATE W/ HOLDER	0	0.00	an *55.00 FS
18	1		*REVERSE SENSOR	0	0.00	m *180.00 FS
19	1		*BOOTLID COMFORT APP	0	0.00	an *40.00 FS
20	1		*BOOTLID COMFORT /TEL NUMBER STICKER	0	0.00	an *60.00 FS
21	1		*BOOTLID ADVERTISEMENT	0	0.00	an *100.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Supp
under cover RH 9108 m

Sub Total (\$\$)	5,896.25
- List Item Discount on L Items (\$\$)	1,092.25
Total Parts (\$\$)	4,804.00

ComfortDelGro Engineering Pte Ltd/SHA2222M/03/01/2022 13:55. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

4145.05
3316.04
3N 435

Supplementary

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Jan 2022)
Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHA2222M/15/01/2022 11:19
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER SIDE UNDER COVER RH	20.00	0.00	*108.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)						108.00
- List Item Discount on L Items (S\$)						21.60
Total Parts (S\$)						86.40

ComfortDelGro Engineering Pte Ltd/SHA2222M/15/01/2022 11:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Qty Particulars

Amount

Miscellaneous Items

1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	PANEL BEATING	New	700	850.00
2	SPRAY PAINTING	New	500	600.00
3	CHECK LIGHTING	New	30	60.00
4	TUFF COATING	New	30	120.00
5	REMOVE/REFIX REVERSE SENSOR	New	30	60.00

Gross Labour Cost (\$\$) 1290 1,690.00

ComfortDelGro Engineering Pte Ltd/SHA2222M/03/01/2022 13:55. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanphin 92495249
'wp' 3/1/22 @ 5 pm
e/s survey after repair
Tanphin @ 11hantow
03 days

3316.04
435
11
1290
5052.04
e/s 4050
03 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance company

Acknowledged by Repairer

Signature:

Date: