

ASS. REC. BY: T. J. J. J.REF: CS/TM/22000039/TI+53

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Aliy

Vehicle: IN / OUT

Veh No: SHA 2222MYr Regn: 2017, March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HyundaiC.C. 1580Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: _____

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHC851CUM4022772

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15R: 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wootake

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 3/1/22Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LUMP SUM \$4050, 3DAYS

RED:2541.4;38%

6591.40

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Rep. Format: _____

Lump Sum / L.B. (\$) _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: **Tokio Marine Insurance Singapore Ltd (HQ)**
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	31/12/2021
Vehicle Reg. No.:	SHA2222M	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	17/03/2017
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEGU329703	Chassis No:	KMHC851CVHU022772
Odometer:	750153 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	4,804.00
Miscellaneous Items	11.00
Labour	1,690.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,505.00
+ GST 7.00% (S\$)	455.35
Nett Amount (S\$)	6,960.35

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 03 Jan 2022)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA2222M/03/01/2022 13:55**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	de *459.40 FL
2	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	de *451.25 FL
3	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	con *394.80 FL
4	2		*REAR BUMPER REINFORCEMENT STAY LH/RH	20.00	0.00	? *276.20 FL
5	1		*REAR BUMPER LOWER CENTRE COVER	20.00	0.00	? *225.00 FL
6	10		*REAR BUMPER CLIPS	20.00	0.00	con *22.00 FL
7	1		*BOOTLID COVER	20.00	0.00	*2,480.40 FL
8	1		*BOOTLID EMBLEM H	20.00	0.00	con *38.00 FL
9	1		*BOOTLID EMBLEM IONIQ	20.00	0.00	con *31.80 FL
10	1		*BOOTLID EMBLEM HYBRID	20.00	0.00	con *24.30 FL
11	1		*REAR BUMPER NUMBER PLATE LAMP	20.00	0.00	? *85.00 FL
12	1		*REAR BUMPER SMART KEY SENSOR	20.00	0.00	? *45.50 FL
13	1		*REAR BUMPER FOG LAMP	20.00	0.00	? *201.10 FL
14	2		*REAR BUMPER BRACKET LH /RH	20.00	0.00	? *111.60 FL
15	2		*REAR BUMPER REFLECTOR LH /RH	20.00	0.00	? *82.90 FL
16	1		*REAR END PANEL	20.00	0.00	Rp *532.00 FL
17	1		*REAR NUMBER PLATE W/ HOLDER	0	0.00	con *55.00 FS
18	1		*REVERSE SENSOR	0	0.00	con *180.00 FS
19	1		*BOOTLID COMFORT APP	0	0.00	con *40.00 FS
20	1		*BOOTLID COMFORT /TEL NUMBER STICKER	0	0.00	con *60.00 FS
21	1		*BOOTLID ADVERTISEMENT	0	0.00	con *100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,896.25
- List Item Discount on L Items (\$\$)	1,092.25
Total Parts (\$\$)	4,804.00

ComfortDelGro Engineering Pte Ltd/SHA2222M/03/01/2022 13:55. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	700 850.00
2	SPRAY PAINTING	New	500 600.00
3	CHECK LIGHTING	New	30 60.00
4	TUFF COATING	New	30 120.00
5	REMOVE/REFIX REVERSE SENSOR	New	30 60.00
Gross Labour Cost (S\$)			1,690.00

ComfortDelGro Engineering Pte Ltd/SHA2222M/03/01/2022 13:55. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanphin 92495249
'up' 3/1/22 @ 5 pm
e/s ready after repair
Tanphin e/hauntan
03 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 03.01.2022 11:09

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO: 305499973

CUSTOMER

VMS COMFORT TRANSPORTATION PTE LTD

CUSTOMER NO. 7010045

ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

L. (R) 65508755

(O)

(P)

SCOUNT CARD NO.

REGN NO:
SHA2222M

MILEAGE

MAKE:
HYUNDAI

FUEL

E.....1/2.....F

MODEL
IONIQ

DATE/TIME IN
01.01.2022 01:30

YR OF MANU.
17.03.2017

TARGET DATE

CHASSIS CODE
KMHC851CVHU022772


COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 31.12.2021

NATURE: 3P 31.12.2021

3/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHA2222M CHIANG

Vehicle No.: SHA2222M

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard