

## Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869

Tel: +65 6255 2288 | Fax: +65 6265 5388

Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

*Not Authorised  
Repairing B&P  
Today*

### ESTIMATION REPORT

Vehicle No : SMK6971X  
Make & Model : RENAULT ,GRAND SCENIC IV 1.5 DCI AT EU6  
VF1RFA00X62476747

Estimation No. : E22010003  
Date : 03/01/2022

| No.                                | Code | Description                                               | Qty  | U/P  | Amt  |
|------------------------------------|------|-----------------------------------------------------------|------|------|------|
| <b>Section: Remark</b> <i>1002</i> |      |                                                           |      |      |      |
| 1                                  |      | ALLIANZ INSURANCE PTE LTD<br>DOA : 30.12.2021<br>TP CLAIM | 1.00 | 0.00 | 0.00 |

Amt S\$ 0.00  
Discount (0.00%) S\$ 0.00  
Subtotal S\$ 0.00

### Section: Parts

|    |            |                              |                    |          |          |   |
|----|------------|------------------------------|--------------------|----------|----------|---|
| 2  | 651004703R | FRONT BONNET                 | <i>B</i> 1.00      | 1,470.12 | 1,470.12 | ✓ |
| 3  | 658408772R | BONNET INSULATOR             | <i>Return</i> 1.00 | 337.32   | 337.32   | ✓ |
| 4  | 654013594R | FRONT BONNET HINGLE LH       | <i>Dry</i> 1.00    | 183.36   | 183.36   | ✓ |
| 5  | 654000247R | FRONT BONNET HINGLE RH       | 1.00               | 183.36   | 183.36   | ? |
| 6  | 654704597R | FRONT BONNET DAMPER RH       | <i>Sn</i> 1.00     | 134.64   | 134.64   | X |
| 7  | 654704597R | FRONT BONNET DAMPER LH       | <i>Sn</i> 1.00     | 134.64   | 134.64   | X |
| 8  | 656016673R | BONNET LOCK                  | <i>Dry</i> 1.00    | 212.52   | 212.52   | ✓ |
| 9  | 620223972R | FRONT BUMPER                 | <i>B</i> 1.00      | 1,554.60 | 1,554.60 | ✓ |
| 10 | 620347326R | FRONT BUMPER SIDE BRACKET RH | <i>Sn</i> 1.00     | 157.20   | 157.20   | X |
| 11 | 620358403R | FRONT BUMPER SIDE BRACKET LH | <i>Dry</i> 1.00    | 157.20   | 157.20   | ✓ |
| 12 | 260101271R | HEADLAMP RH                  | <i>my cm</i> 1.00  | 984.84   | 984.84   | ✓ |
| 13 | 260602165R | HEADLAMP LH                  | <i>my cm</i> 1.00  | 984.84   | 984.84   | ✓ |
| 14 | 269257264R | HEADLAMP BRACKET LH/RH       | 1.00               | 183.60   | 183.60   | ? |
| 15 | 622907255R | FRONT CENTRE BRACE BRACKET   | <i>B</i> 1.00      | 138.12   | 138.12   | ✓ |
| 16 | 620363937R | FRONT RADIATOR TOP GANNISH   | <i>CM</i> 1.00     | 478.08   | 478.08   | ✓ |
| 17 | 628905855E | EMBLEM                       | <i>Sn</i> 1.00     | 178.08   | 178.08   | ✓ |
| 18 | 623821034R | RADIATOR GRILLE BLACK        | <i>CM</i> 1.00     | 302.76   | 302.76   | ✓ |
| 19 | 623855072R | RADIATOR GRILLE OUTER CHROME | <i>nu</i> 1.00     | 376.80   | 376.80   | ✓ |
| 20 | 622561964R | RADIATOR GRILLE              | <i>CM</i> 1.00     | 495.72   | 495.72   | ✓ |
| 21 | 261520089R | FOGLAMP COVER LH AND RH      | <i>Sn</i> 2.00     | 266.16   | 532.32   | X |

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Continue on next page...

## Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869

Tel: +65 6255 2288 | Fax: +65 6265 5388

Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

### ESTIMATION REPORT

Vehicle No : SMK6971X

Make & Model : RENAULT ,GRAND SCENIC IV 1.5 DCI AT EU6  
VF1RFA00X62476747

Estimation No. : E22010003

Date : 03/01/2022

| No. | Code | Description                                         | Qty    | U/P      | Amt      |    |
|-----|------|-----------------------------------------------------|--------|----------|----------|----|
| 22  |      | 261A24871R FOGLAMP CHROME LH AND RH                 | 2.00   | 266.16   | 532.32   | 7  |
| 23  |      | 261520089R FRONT FOG LAMP LH /RH                    | 2.00   | 266.16   | 532.32   | X  |
| 24  |      | 253A44101R FRONT PAKING SENSOR                      | 2 4.00 | 291.60   | 1,166.40 | 4T |
| 25  |      | 874519982R FRONT BUMPER SENSOR WIRE HARNESS         | 1.00   | 310.80   | 310.80   | 7  |
| 26  |      | 284389618R FRONT BLIND SPOT SENSOR                  | 2.00   | 457.92   | 915.84   | 7  |
| 27  |      | 620901789R FRONT BUMPER REINFORCEMENT               | 1.00   | 795.24   | 795.24   | 7  |
| 28  |      | 620901789R FRONT BUMPER REINFORCEMENT LOWER GARNISH | 1.00   | 271.80   | 271.80   | ✓  |
| 29  |      | 625005785R FRONT SUPPORT PANEL                      | 1.00   | 1,231.68 | 1,231.68 | ✓  |
| 30  |      | 7711428130 FRONT ENGINE COOLANT 5L                  | 1.00   | 29.40    | 29.40    | ✓  |
| 31  |      | 921004063R FRONT ENGINE AIRCON CONDENSER            | 1.00   | 1,173.60 | 1,173.60 | 7  |
| 32  |      | 144614EA1B FRONT ENGINE INNER COOLER                | 1.00   | 915.00   | 915.00   | 7  |
| 33  |      | 214105169R FRONT ENGINE RADIATOR                    | 1.00   | 801.96   | 801.96   | 7  |
| 34  |      | 214819674R FRONT ENGINE FAN COWLING ASSY            | 1.00   | 1,010.40 | 1,010.40 | 7  |
| 35  |      | 631012967R FRONT FENDER LH                          | 1.00   | 737.76   | 737.76   | ✓  |
| 36  |      | 631009903R FRONT FENDER RH                          | 1.00   | 737.76   | 737.76   | X  |
| 37  |      | 214F62853R FRONT LOWER AIR INTAKE FLAP GUIDE        | 1.00   | 634.68   | 634.68   | 7  |
| 38  |      | 622568767R FRONT LOWER FLAP GUIDE INNER AIR DUCT    | 1.00   | 264.00   | 264.00   | ✓  |
| 39  |      | 215586371R INTERCOOLER AIR DUCT                     | 1.00   | 61.44    | 61.44    | 7  |
| 40  |      | 215595656R RADIATOR INNER AIR DUCT                  | 1.00   | 117.48   | 117.48   | 7  |
| 41  |      | 628109433R RADIATOR GRILLE INNER AIR DUCT           | 1.00   | 216.00   | 216.00   | 7  |
| 42  |      | 214G39170R BUMPER AIR INTAKE HARNESS FRT RH GS4     | 1.00   | 79.96    | 79.96    | 7  |
| 43  |      | 214G39170R BUMPER AIR INTAKE HARNESS FRT RH GS4     | 1.00   | 95.95    | 95.95    | 7  |

Continue on next page...

## Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869  
Tel: +65 6255 2288 | Fax: +65 6265 5388  
Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

### ESTIMATION REPORT

Vehicle No : SMK6971X  
Make & Model : RENAULT ,GRAND SCENIC IV 1.5 DCI AT EU6  
VF1RFA00X62476747

Estimation No. : E22010003  
Date : 03/01/2022

| No. | Code | Description | Qty | U/P | Amt                       |
|-----|------|-------------|-----|-----|---------------------------|
|     |      |             |     |     | Amt S\$                   |
|     |      |             |     |     | 21,811.91                 |
|     |      |             |     |     | Discount (0.00%) S\$ 0.00 |
|     |      |             |     |     | Subtotal S\$              |
|     |      |             |     |     | 21,811.91                 |

#### Section: Special nett

|    |  |                                        |      |      |                           |   |
|----|--|----------------------------------------|------|------|---------------------------|---|
| 44 |  | FRONT BUMPER CLIPS                     | 6.00 | 7.00 | 42.00                     | — |
| 45 |  | RADIATOR TOP GANISH SCREWS             | 6.00 | 7.00 | 42.00                     | — |
| 46 |  | FRONT FENDER INNER SPLASH SHIELD CLIPS | 6.00 | 7.00 | 42.00                     | ? |
|    |  |                                        |      |      | Amt S\$ 126.00            |   |
|    |  |                                        |      |      | Discount (0.00%) S\$ 0.00 |   |
|    |  |                                        |      |      | Subtotal S\$ 126.00       |   |

#### Section: Labour

|    |  |                                                                                                                                                                                                  |      |          |          |       |
|----|--|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|----------|----------|-------|
| 47 |  | TO REMOVE & REFIX, REPAIR, KNOCKING, WELDING FRONT PORTION, FRONT BUMPER, FRONT FENDER LH/RH, CHASSIS LH/RH AND DAMAGE AREA                                                                      | 1.00 | 1,800.00 | 1,800.00 | Pool  |
| 48 |  | TO RESPRAY FRONT PORTION, BONNET INNER / OUTER , FRONT BUMPER, FRONT FENDER LH & RH AND POLISH DAMAGE AREAS                                                                                      | 1.00 | 1,200.00 | 1,200.00 | Steel |
| 49 |  | TO CHECK ALL WIRING FOR OPERATION AND PARKING SENSOR FOR OPERATION                                                                                                                               | 1.00 | 120.00   | 120.00   | } 2cl |
| 50 |  | TO CHECK AND ADJUST HEADLAMP LH/RH FOCUS                                                                                                                                                         | 1.00 | 120.00   | 120.00   |       |
| 51 |  | TO REMOVE/INSTALL RADIATOR COOLING SYSTEM & ALL NECESSARY PARTS TO FACILITATE REPAIR INCLUDING PRESSURE TEST, BLEED COOLING SYSTEM & CHECK LEAKS FOR REPLACE FRONT SUPPORT PANEL AND DAMAGE AREA | 1.00 | 250.00   | 250.00   | 6cl   |
| 52 |  | TO CONDUCT RE-PROGRAMME AND SETTING OF ECU SYSTEM TO CLEAR FAULT CODE                                                                                                                            | 1.00 | 380.00   | 380.00   | ?     |
| 53 |  | TO JACKING OF CHASSIS LH/RH AND MOUNTING OF CAR ON CELET BENCH INCLUDING TO REPLACE DAMAGED PARTS                                                                                                | 1.00 | 250.00   | 250.00   | nn X  |

Continue on next page...

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869  
Tel: +65 6255 2288 | Fax: +65 6265 5388  
Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

Tel: +65 6255 2288 | Fax: +65 6265 5388

Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

**Estimation No.** : E22010003  
**Date** : 03/01/2022

**Vehicle No** : SMK6971X  
**Make & Model** : RENAULT ,GRAND SCENIC IV 1.5 DCI AT EU6  
,VF1RFA00X62476747

50/  
100/

|                         |              |
|-------------------------|--------------|
| <b>Amt</b>              | S\$ 4,420.00 |
| <b>Discount (0.00%)</b> | S\$ 0.00     |
| <b>Subtotal</b>         | S\$ 4,420.00 |

ALLIANZ INSURANCE PTE LTD  
DOA : 30.12.2021  
TP CLAIM

S\$ 26,357.91